3800-FM-BCW0271g Rev. 11/2022 Chapter 102 Inspection Report



COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF CLEAN WATER

CHAPTER 102 INSPECTION REPORT

PA Department of Environmental Protection

Permit No.: PAD510225

Clear Report

Save as PDF

Report No.: 20

	GENERAL INFORM	ATION		
Project/Site Name:	Alliance 51 st Street, Philadelphia	Permit Issuance Date:	9/5/2023	
Site Address:	1656 S. 51 st St.	Permit Expiration Date:	9/4/2028	
Site City, State, ZIP:	Philadelphia, PA 19143	Permit Type:	NPDES IP	
RP/Permittee Name:	Eric Carlson	Site Municipality(ies):	Philadelphia	
RP/Permittee Address:	40 Morris Ave., Suite 230	Site County(ies):	Philadelphia	
RP/Permittee City, State, Z	ZIP: Bryn Mawr, PA 19010	Earth Disturbance:	11.54	acres
RP/Permittee Email:	ecarlson@alliancehp.com	Site Latitude:	39.935278	
Surface Water(s):	Schuylkill River	Site Longitude: -	75.209236	
Special Protection?	🗌 Yes 🖾 No	Complaint Inspection?	🛛 Yes	🗌 No
Construction Stage:	Inactive	Activity:	Construction	⊧ <u>></u> 1 ac.
Operator Name	Operator Company	Operator E	mail	Approved
n/a				
		IATION		
Inspection Date:	4/2/25	Inspection Time:	11:45	АМ 🗌 РМ
Lead Inspector Name:	Robert Page	Inspector Email:	ropage@pa.ge	vc
Inspector Title: Env. Grp. Mgr.		Inspector Phone:	484.250.5104	
Other Inspector(s):	n/a	Weather:	Partly cloudy,	52°F
Was a representative of the	e project on-site during the inspection?	🗌 Yes 🖾 No		
Representative Name:	n/a	Email: n/a		
Representative Company:	n/a	Phone: n/a		
Type of Inspection:	Initial 🛛 Follow-up (Previous R	eport #19)	Photographs	attached
Brief description of the site	and summary of observations:			
	cted a Chapter 102 inspection of this indu etween July 18, 2024 and March 26, 202		(reference prev	vious
No permittee representativ Street and the Bartram's G	es were present; I did not enter the site a Garden trail.	and took all pictures and o	bservations fro	m 51st
	along both 51 st St. gates to the site were i ared to remain relatively uniform.	in proper position and in g	lood operating	condition.
The stone stockpile near th "For Lease" signage remai	ne 51 st St. midslope site boundary appea ns in place.	red unchanged from the p	revious inspec	tion. The
I observed some germinati	on towards the downslope boundary of the	he site at the time of this i	nspection.	
		(summ	ary continued c	n Page 4)

		INSPECTION FINDINGS	
	\boxtimes	No violations observed at this time.	
a.		Failure to implement and/or maintain E&S BMPs for earth disturbance (§§ 102.4(b)(1), 102.22(a)(1)).	
b.		Failure to develop and/or implement a written E&S Plan (§ 102.4(b)(2)).	
c.		Failure to have a person trained and experienced in E&S control methods develop an E&S Plan (§ 102.4(b)(3)).	
d.		Failure to have the E&S Plan and/or inspection/monitoring reports on-site and available for review (§ 102.4(b)(8)).	
e.		Failure of permittee to obtain all necessary approvals/permits from DEP/CCD prior to commencing earth disturbance (§ 102.4(d)).	
f.		Failure to hold a pre-construction meeting and/or invite DEP/CCD staff and/or provide at least 7 days' notice (§ 102.5(e)).	
g.		Failure of an operator to submit a co-permittee acknowledgement form (§ 102.5(h)).	
h.		Failure to prepare and/or implement and/or provide upon request a PPC Plan when required (§ 102.5(I)).	
i.		Failure to temporarily stabilize areas where there will be a cessation of earth disturbance activities for at least 4 days (§ 102.22(b)).	
j.		Failure to complete or accurately complete visual site inspections as required by the permit (CSL § 402(b)).	
k.		Failure to implement PCSM BMPs as specified in the approved PCSM Plan (§ 102.8(a)).	
I.		Failure to operate and maintain PCSM BMPs as specified in an approved PCSM Plan or deed (§ 102.8(a)).	
m.		Failure to have the PCSM Plan, inspection reports, and/or monitoring records available for review (§ 102.8(j)).	
n.		Failure to have a licensed professional or a designee present on-site during critical stages of PCSM BMPs (§ 102.8(k)).	
О.		Failure to record an instrument for PCSM BMPs (§ 102.8(m)(2)).	
p.		Failure to meet riparian forest buffer criteria (§ 102.14(b)).	
q.		Failure to permanently stabilize a project site or any phase or stage thereof (§ 102.22(a)).	
r.		Failure to remove temporary E&S BMPs once permanent stabilization has been established (§ 102.22(a)(1)).	
S.		Failure to obtain NPDES permit prior to commencing earth disturbance activity with at least one acre of disturbance (§ 102.5(a)).	
t.		Failure to obtain E&S permit prior to commencing earth disturbance activity with at least 25 acres of disturbance for timber harvesting and road maintenance (§ 102.5(b)).	
u.		Failure to obtain E&S permit prior to commencing earth disturbance activity with at least 5 acres of disturbance for oil and gas activities (§ 102.5(c)).	
٧.		Failure of activity not requiring a permit to comply with Chapter 102 requirements (§ 102.5(k)).	
w.		Failure to follow the approved construction sequence in an E&S or PCSM Plan (CSL § 402(b)).	
х.		Failure to submit a Notice of Termination (NOT) (§ 102.7(a)).	
у.		Unauthorized discharge of polluting substances to waters of the Commonwealth resulting in pollution (CSL § 401).	

		Failure to comply with the terms and conditions of a permit or order (CSL § 402(b)).		
aa.		Failure to remove building materials and/or wastes from the site for recycling or disposal in accordance with DEP regulations as required by the permit (CSL § 402(b)).		
bb.		Failure to comply with DEP regulations or the Clean Streams Law (CSL § 611).		
cc.		Failure to take necessary measures to prevent pollutants from reaching waters of the Commonwealth (§ 91.34(a)).		
dd.		Failure to notify DEP of new or expanded earth disturbance not identified in an NPDES permit application (§ 92a.24(b)).		
ee.		Failure to notify and/or obtain authorization from DEP/CCD for changes to NPDES permitted activities (§ 92a.41(a)(12)).		
ff.	Other:			
		During the inspection violations of Chapter 105 were observed and are identified in a separate Chapter 105 inspection report.		
		E&S BMPs were evaluated and appear to be functioning as designed.		
		PCSM BMPs were evaluated and appear to be functioning as designed.		
		Form 3800-FM-BCW0531a was used to document the PCSM BMP evaluation.		
		There is a need for modifications to the E&S Plan, PCSM Plan, or permit coverage.		
		Describe:		
		COMPLIANCE ASSISTANCE RECOMMENDATIONS		
1. In accordance with DEP's Erosion and Sediment Pollution Control Program Manual, Technical Guidance No. 363- 2134-008 (March 2012), Page 65, inspect filter socks weekly and after each runoff event. In addition, DEP requests that damaged socks be repaired according to manufacturer's specifications or replaced within 24 hours of inspection.				
dama				
	ged s			
2. Ma	ged s intain	ocks be repaired according to manufacturer's specifications or replaced within 24 hours of inspection.		
2. Ma 3. It is site. 4. Sir	ged s intain reco	ocks be repaired according to manufacturer's specifications or replaced within 24 hours of inspection.		
2. Ma 3. It is site. 4. Sir for sit	ged s intain reco nce th e stat	ocks be repaired according to manufacturer's specifications or replaced within 24 hours of inspection. ing filtersock areas, to prevent any overtopping condition, is recommended. mmended to investigate the addition of a storage BMP (i.e., a sediment basin) in the downslope portion of the e growing season is approaching as of the time of this inspection, DEP recommends considering strategies bilization at this time.		
 2. Ma 3. It is site. 4. Sir for sit 5. Re 	ged s intain reco nce th e stat	ocks be repaired according to manufacturer's specifications or replaced within 24 hours of inspection. ing filtersock areas, to prevent any overtopping condition, is recommended. mmended to investigate the addition of a storage BMP (i.e., a sediment basin) in the downslope portion of the e growing season is approaching as of the time of this inspection, DEP recommends considering strategies bilization at this time.		
 2. Ma 3. It is site. 4. Sir for sit 5. Re 	ged s intain reco nce th e stat	ocks be repaired according to manufacturer's specifications or replaced within 24 hours of inspection. ing filtersock areas, to prevent any overtopping condition, is recommended. mmended to investigate the addition of a storage BMP (i.e., a sediment basin) in the downslope portion of the e growing season is approaching as of the time of this inspection, DEP recommends considering strategies bilization at this time.		
 2. Ma 3. It is site. 4. Sir for sit 5. Re 	ged s intain reco nce th e stat	ocks be repaired according to manufacturer's specifications or replaced within 24 hours of inspection. ing filtersock areas, to prevent any overtopping condition, is recommended. mmended to investigate the addition of a storage BMP (i.e., a sediment basin) in the downslope portion of the e growing season is approaching as of the time of this inspection, DEP recommends considering strategies bilization at this time.		
 2. Ma 3. It is site. 4. Sir for sit 5. Re 	ged s intain reco nce th e stat	ocks be repaired according to manufacturer's specifications or replaced within 24 hours of inspection. ing filtersock areas, to prevent any overtopping condition, is recommended. mmended to investigate the addition of a storage BMP (i.e., a sediment basin) in the downslope portion of the e growing season is approaching as of the time of this inspection, DEP recommends considering strategies bilization at this time.		
 2. Ma 3. It is site. 4. Sir for sit 5. Re 	ged s intain reco nce th e stat	ocks be repaired according to manufacturer's specifications or replaced within 24 hours of inspection. ing filtersock areas, to prevent any overtopping condition, is recommended. mmended to investigate the addition of a storage BMP (i.e., a sediment basin) in the downslope portion of the e growing season is approaching as of the time of this inspection, DEP recommends considering strategies bilization at this time.		
 2. Ma 3. It is site. 4. Sir for sit 5. Re 	ged s intain reco nce th e stat	ocks be repaired according to manufacturer's specifications or replaced within 24 hours of inspection. ing filtersock areas, to prevent any overtopping condition, is recommended. mmended to investigate the addition of a storage BMP (i.e., a sediment basin) in the downslope portion of the e growing season is approaching as of the time of this inspection, DEP recommends considering strategies bilization at this time.		
 2. Ma 3. It is site. 4. Sir for sit 5. Re 	ged s intain reco nce th e stat	ocks be repaired according to manufacturer's specifications or replaced within 24 hours of inspection. ing filtersock areas, to prevent any overtopping condition, is recommended. mmended to investigate the addition of a storage BMP (i.e., a sediment basin) in the downslope portion of the e growing season is approaching as of the time of this inspection, DEP recommends considering strategies bilization at this time.		
 2. Ma 3. It is site. 4. Sir for sit 5. Re 	ged s intain reco nce th e stat	ocks be repaired according to manufacturer's specifications or replaced within 24 hours of inspection. ing filtersock areas, to prevent any overtopping condition, is recommended. mmended to investigate the addition of a storage BMP (i.e., a sediment basin) in the downslope portion of the e growing season is approaching as of the time of this inspection, DEP recommends considering strategies bilization at this time.		

Permit No.: PAD510225 Report No.: 20

ADDITIONAL COMMENTS

(continued from Page 1)

Erosion control matting remained in place at the interior bend of the large fill dirt stockpile. I did not observe any significant germination occurring on the stockpile.

I observed that some short stretches of filtersock along the downslope boundary of the site were nearing an overtopping condition by collected mulch from upslope areas.

The black tarp covering the small pile of contaminated soil downslope of the large fill dirt stockpile had again appeared to be mostly blown off the pile and indicated signs of shredding. Perimeter control (filter sock) around this pile, and the downslope site perimeter, remained intact.

One inlet protection filter sock was in place along the wall of the Bartram's Garden trail.

I did not observe any change to the sediment staining on the Bartram's Garden trail downslope of the site.

In accordance with the site's NPDES Permit No. PAD510225, Section III.C., DEP requests copies of the two most recent Visual Site Inspection Reports (as of April 2, 2025) and any accompanying photos. DEP requests this information by April 11, 2025.

No violations noted during this inspection.

DEP will be continuing to follow up on this site, and Robert Page can be reached at 484.250.5104 or ropage@pa.gov.

NOTICE AND SIGNATURES

This report is official notification that a representative of the Department of Environmental Protection (DEP) has conducted an inspection of your earth disturbance activity to determine compliance with 25 Pa. Code Chapter 102 and the Pennsylvania Clean Streams Law. This representative may be an employee of a County Conservation District (CCD), which by delegation agreement with DEP is authorized to investigate complaints, inspect earth disturbance activities and conduct compliance actions. Any violations observed by DEP/CCD have been noted in this report and constitute unlawful conduct as defined in Section 611 of the Clean Streams Law. Failure to take corrective actions to resolve the violations may result in administrative, civil and/or criminal penalties being assessed by DEP as as specified at Section 602 of the Clean Streams Law. The Clean Streams Law provides for up to \$10,000 per day in civil penalties, up to \$10,000 in summary criminal penalties, and up to \$25,000 in misdemeanor criminal penalties for each violation. This report does not constitute an Order or appealable action of DEP. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein. For further information or assistance contact the DEP/CCD inspector.

The Project Site Representative's signature acknowledges that they have read the report and were given an opportunity to discuss the report with the inspector. The signature does not necessarily mean the signee agrees with the report. All comments by the inspector are based on visual site observations and do not constitute professional practice under applicable law.

Violations are documented in this report and this report serves as a Notice of Violation (NOV).

A follow-up inspection will occur on or about: **ongoing**

RobertEPz

4/4/25


Site Representative Signature

Date

Inspector Signature

Date

cc: Philadelphia Water Department







Downslope filtersock (foreground); contaminated fill dirt stockpile without tarp (at center); downslope end of large fill dirt stockpile with erosion matting (background).



