

Office of Active and Abandoned Mine Operations

GLENWHITE (NORTH SITE)
Abandoned Mine Reclamation Project
Contract No. OSM 07(4339)104.1

Bureau of Abandoned Mine Reclamation 286 Industrial Park Road Ebensburg, PA 15931-4119

DEPARTMENT OF ENVIRONMENTAL PROTECTION OFFICE OF ACTIVE AND ABANDONED MINE OPERATIONS BUREAU OF ABANDONED MINE RECLAMATION

GLENWHITE (NORTH SITE) ABANDONED MINE RECLAMATION PROJECT CONTRACT NO. OSM 07(4339)104.1

FACT SHEET

<u>Location:</u> The project site is located in Logan Township, Blair County. The site can

accessed from the William Penn Highway, State Route (S.R.) 22, Gallitzin E by traveling 1.3 miles north on Tunnel Hill Street. The road name changes Coupon Gallitzin Road (S.R. 1015). After traveling 2.8 miles on Coup Gallitzin Road (S.R. 1015), turn right onto a mining access road. After traveli approximately 3.0 miles, the site is located at the end of the mining access road.

Watershed: Glenwhite Run, Cold Water Fishes (CWF), and Kittanning Run, CWF

Official Start Date: September 19, 2020

Contract Completion Date: September 2, 2022

Contractor: Ligonier Construction

Property Owners: Gerald P. Neugebauer, Jr., Trustee

Angels' Coal Trust 219 South Center Street Ebensburg, PA 15931

Project Cost: \$1,575,182.18 (Final), \$1,555,713.00 (Bid Amount)

Project Area: 40 Acres

Purpose: To eliminate eligible abandoned mine public health and safety hazards that ε

located within close proximity to places of intense visitation of humans.

Description: One Dangerous Highwall (DH) measuring 35 feet high and 1,900 linear fe

long and one nearly vertical dangerous pile (DP) measuring, over 60 feet hi was eliminated by using the associated spoil to backfill and reclaim the DH. T DP, locally known as "Big Murf" was regraded and re-vegetated to eliminate t near vertical slope conditions. The site was accessed heavily by the public whi was evident from all-terrain vehicles (ATVs) and motorcycle tracks and tra including a fire ring and empty bottles and cans found above the highwar Locals reported large groups would congregate, drink and climb the slopes a several visitors were hurt while at the site. These reclaimed abandoned mi land features, located within Problem Area 4339 (PA4339), met the Office Surface Mining Reclamation and Enforcement's Priority 2 criteria. PA4339 referenced within the Ashville and Altoona 7.5 Minute USGS Quadrangle Maj The dangerous condition was a direct result of surface and auger mini

performed in the early 1950s by the Cavalier Coal Company.

Funding: Pennsylvania's Abandoned Mine Land Program

Project Management: Bureau of Abandoned Mine Reclamation

Cambria District Office

814.472.1800

Accomplishments:

TY	#	AMLF KEYWO	MEASUREMENTS						ITY	
PRIORI	AMLF		ACRES	HEIGHT	LENGTE	COUNT	VOL.	FLOW	QUANT	UNI
2	4438-17	DH	-	-	1,900	-	-	-	1,900	L.F.
2	4438-18	DPE	15	-	1	-	-	ı	15	ACRES
2	4438-20	SA	31	-	-	-	ı	ı	31	ACRES


AMLF = Abandoned Mine Land Feature

DH = Dangerous Highwall

DPE = Dangerous Pile and Embankment

SA = Spoil Area L.F.= Linear Feet

Location Map



Pre-Construction





During Construction





During Construction





Post-Construction



