2700-FM-BAQ0023 2/2015 pennsylvania Department of Environmental Protection	INS	NSPECTION REPORT			Commonwealth of Pennsylvania Department of Environmental Protection Air Quality Program			
Date(s) of Inspection: TV D PA D SM GP D	Permit #(	s):	Expiratio	n Date:	Case	#: PF	= ID #:	
8 22 23 NM D MEGA D				<u></u>			151121	
Company Name: HELDELBORG MATERIALS /	Municipa	-			Cour	-		
				TOWNSHIP N. ROCKHILL ROMA		BUCKS COUNTY Federal ID — Plant Code #:		
EAST RUCKHILL QUARRY SELLERINLLE , PA Responsible Official:			Mailing Address:					
•								
ANDREW GUTSHALL Title:			HEIDELBERG MATERIALS					
AREA ENVIRONMENTAL MAN Phone #(s):	AGER		7660 IMP6			RIAL WAT		
610-366-4819			ALLENTOWN, PA 18195					
Mark (X) All Inspection Types Tha	at Apply	To This In			<u>,                                     </u>			
Full Compliance Evaluation (FCE)		Plan Approval Inspection				File Review (FR)		
Operating Permit Inspection (PI)	Initial F	Initial Permit Inspection (IPI)				Complaint Inspection	(Cl)	
Routine/Partial (RTPT)		Follow-Up Inspection (Ref. Date:		)		Sample Collection (S	· · ·	
Minor Source(s) Inspection (RFD)	Stack	Stack Test Observation				Multi-Media Inspection	n (MM)	
Other:	] Annou	Announced						
Annual Compliance Certification Received:	nual Compliance Certification Received: YES NO NO N/A			Date Received	d:			
AIMS Report Received:								
Mark (X) All Activities That Apply								
File Review	Pre-In	Pre-Inspection Briefing				Exit Interview/Briefing	1	
Pre-Inspection Observations	Check	Check For New/Unreported Sources				Sample(s) Collected		
Visible Emissions Observations	Verify	Operation of CE	EMS	•		Other		
Comments/Recommendations:						Yes 🗌 No (If yes		
I ARRIVED AT THE SITE AT 8.50	D AM 1	O OBERVET	HC LIMI	TED ACTIVITY	AIR	SPMPLING EVENT	NO. 4 (SOUTIN ROMO	
IPPON ARRIVAL I MET WITH AIN	AEC BUL	NGTER NAC	PARRE	N HENRY (I	DEP	MINING ). I M	IET MOREN	
GUISHTML AND PRANK TEDESCO WHO WERE RUNNING THE WATER TRUCK AND THE RUBBER TIRE								
LOADER . J ALSO MET NITH KR								
NHO WERE CONDULTING THE SAM	PUNG.	I OBSERVE	D FIVE	TRUCKS O	<u>N 5</u>	TE AT DIFFERENT	T TIME, THE	
RUBBER TIRE LONDER MOVED AB	<u>ÚNT 20</u>	ton of Ac	rease and	FROM TH	τo	TUCKPILE TO IT	TRUNCK-I	
OBJERUED THE TRUCKS AFTER BEING LUMDED WITH AGOREGANTE AT THE EXIT, THE WATER TRUCK								
WAN UNED TO WARH THE TRUCK HHEELS. I OBSERVED THAT APTER EACH ROUND OF LOAD LEFT								
THE QUARRY, THE WATER TRUCK								
PREVENT ONST QURINE ALTIVIEY.	1.0BE	rved a s	rkgot sl	405PBR PRO	m	SCA ON SITE , S	STREET SHEEPBC	
Compliance Status: 🔲 In 🗌 Out 🗌 Pe	nding 🗌	Awaiting Co.	Report	Nee	ds a	Follow-Up Inspection	? 🗌 Yes 🗌 No	
	Title:			Signature:			Date:	
		PERMIT MO	5yZ.				8 22 23	
	Title:	$\overline{1}$		Signature:			Date/Time:	
Karen Mittaker (UVIRGNMENTAL RAINEE 8-22-2083) This document is official notification that a representative of the Department of Environmental Protection, Air Quality Program, inspected the identified site. The findings of this								
inspection are shown above and on any attached pag sample results or from any additional review of Departm	jes, and may	include violation	s uncovered	during the inspec	ction.	violations may also be dis		
Page of eFacts Inspect	tion ID#:	360382	Date:		_ F	teviewed By		

] White – Regi	ional Office
----------------	--------------

in and Weren
I CASESE OBSERVED TESTER B FOLLOW AND SHEEP BETAND EACH TRUCK THAT WOULD FXIT
THE WIFE.
J ORSERVED ALL & NAME ING LOCATIONS AT DIFFORENT TIMES NURING THE ACTIVITY AND
CONFIRMED THAT THERE WERE TWO PUMPS AT EACH LOCATION (8-HOUR FLOW RATE PUMP
AND THE 4-HOUR PLOW RATE PUMP). DURING ONE OF MY OBSERVATION THE 8 HOUR PLON
BATE PUMP AT LOLATION 3 STOPPED WORKING WHEN TRYING TO GET THE READING AT 9.16AM
MR KRISTAN WITT REPLACED THE PUMP AND I WAS ABLE TO OBTAIN ROADING AT 9.18AM.
ALL THE PUMPS WORE OPERATING PROPORCY", I CONFIRMED THE FLOW RATES FOR SEVERAL
LOCATIONS IN THE MORNING AND AFTERNOON.
THE WEATHER CUNDITIONS THROUGH OUT THE DAY WERE DRY AND WINDY I DID NOT
OBJERVE ANY DUST DURING THE ACTIVITY , NOR ON DITE. THE WIND SPEED / DIRECTION RANGED
BETMEEN S-9 MPH AND DIRECTION WAS NORTH EAST.
I REMAINED ON SITE UNTIL THE SAMPLING WAS TO COMPLETE
ME GUIJHALL STATED THAT 24 TRUCKS WENT CUT TUDAY.
· ·
· · · · · · · · · · · · · · · · · · ·
· · · · · · · · · · · · · · · · · · ·
Company plant name: HEIDELBERG MATERIALY Initials of representative interviewed: Date: EAST A-WILL BLARD
LINI ROREFILL OUTIVES
Page of Reviewed By

## 8/22/23 Heidelberg Materials East Rockhill Quarry Sampling Photos



Sampling Location 3-8/22/23, 9:19am



Sampling Location 4-8/22/23, 9:22am



Sampling Location 5-8/22/23, 9:27am



Sampling Location 6-8/22/23, 9:30am



Sampling Location 1-8/22/23, 9:38am



Sampling Location 8-8/22/23, 9:43am



Sampling Location 7-8/22/23, 9:46am



Sampling Location 2-8/22/23, 10:01am



Water truck wetting the roadway- 8/22/23,10:17am



Rubber tire loader loading the truck with aggregate from stockpile- 8/22/23, 1136am



Water truck being used to wash the wheels of the truck-8/22/23, 1024am