

Commonwealth of Penn

DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF SURFACE MINE RECLAMATION  
INSPECTION  
REPORT

Min it No. 733-5  
Drainage Permit No. 79748711  
Mine Inspection No. 5-54  
Reinspection No. 1-79

Company <u>General Crushed Stone Co</u>		Mine Location: County <u>Bucks</u>	Township <u>E. Rookhill</u>
Mining Permit Acres Affected <u>45</u>		Drainage Permit Acres Affected <u>65</u>	
Status of Operation: Active <u>X</u>	Inactive	Not Started	

1. Is this operation in compliance with the Safety Rules and Regulations? YES X NO      NOTED
2. Is this mine operating in compliance with the conditions of the mining permit? YES X NO      NOTED X
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES X NO      NOTED X

REMARKS AND RECOMMENDATIONS: Discharge at railroad switch is clear  
Test hole in "woods road" has been plugged.  
"Mining Plan" property map shows the  
future limit of mining as Elevation 464 ft.  
The "existing diversion ditches" as shown  
on the Mine Drainage Plan are in  
need of upgrading & repair etc. The  
South and So. East area to be reviewed  
by the Operator.  
The #6 basin is again filling up with  
silt - should be cleaned out before  
the discharge is affected adversely.

Company Official Contacted <u>James Fryer</u>	Title <u>Supt.</u>
Mine Inspector <u>Paul T. Seifert</u>	Inspection Date <u>5-7-79</u>

INSPECTORS' RECOMMENDATIONS TO BUREAU: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_