



**2025
Industrial Mineral Inspection Assignments**

Mine Inspector	Operation	PF Number
Walsh 724-498-9039	Charmian Plant	03460
	Crystal Cave	C226
	Indian Echo Caverns	C228
	Kaylor Mine – 3 Plant	03950401
	Kaylor Mine – 3 UG Storage	S-102
	Kaylor Mine 4	M-135
	Lost Rivers Caverns	C231
	Millard Mine (Non-Active)	09058
	Penn’s Cave	C232
	Pleasant Gap Mine	06468
	Pleasant Gap Plant (Graymont)	P215
	Romesburg Quarry	09310
	Thomasville Mine (Plant)	00251
	Thomasville 1,2,3	03432
	Whitney North (Non-Active)	
Woodward Cave	C233	
Yackmack 724-525-8077	Annadale Mine (Iron Mountain)	S111
	Armstrong Cement	00215
	Bakersville III Quarry	09657
	Bison Mine	10107
	Creekside Mushroom	M105
	Jim Houk Mine – 1 (Non-Active)	09592
	Latrobe Mine (Non-Active)	00131
	M&M Lime	04403
	Shenango Mine	10351
	Sno-Top Mine	S114
	South Bend (IDLE)	10232
	Torrance Mine & Surface Prep	08484
	US Storage – Toys UG Storage Mine	M109
	Wampum Underground	S112
Goodwin 724-552-9308	Buckeye Quarry – Eichorn	05464
	Bullskin No. 1	10047
	Coolspring Mine 1 (DMC)	M-138
	Coastal Quarry	00155
	Coral Cave	C225
	Dunbar Mine	M118
	Indian Caverns	C227
	Lake Lynn Quarry	08891
	Laurel Caverns	C229
	Lincoln Caverns	C230
	Rich Hill Mine #2	08864
	Springfield Pike Quarry	00047