

---

**From:** Fazzino, Chelsea  
**Sent:** Monday, September 30, 2019 3:47 PM  
**To:** Larry.Gremminger@energyTransfer.com  
**Cc:** Staron, Richard; Hohenstein, John; Henning-Dudley, Desiree; Yordy, Karyn  
**Subject:** re-evaluation comments - SPLP HDD No. S3-0331, Eagleview Boulevard

Good afternoon Larry,

I have reviewed your HDD re-evaluation for HDD331 and, similarly to the last reevaluation for which we exchanged correspondence, have a comment that I am requesting that you provide additional information to address.

- Regarding the last bullet point in the Conclusion section of the HDD analysis: The discussion of how a determination is made as to whether a LOC is small vs. large to determine the next steps. DEP requests that a responsible professional be on site to monitor the LOCs and make a determination as to which LOCS will require remediation.

If you would like to discuss this further, feel free to give me a call.

Thanks,  
Chelsea

**Chelsea Fazzino, P.G.** | Licensed Professional Geologist  
Department of Environmental Protection | Southeast Regional Office  
2 East Main Street | Norristown, PA 19401  
Phone: 484.250.5791 | Fax: 484.250.5961  
[www.dep.pa.gov](http://www.dep.pa.gov)

**PRIVILEGED AND CONFIDENTIAL COMMUNICATION**

*The information transmitted is intended only for the person or entity to whom it is addressed and may contain confidential and/or privileged material. Any use of this information other than by the intended recipient is prohibited. If you receive this message in error, please send a reply e-mail to the sender and delete the material from any and all computers. Unintended transmissions shall not constitute waiver of the attorney-client or any other privilege.*