5600-FM-MR0005.7 Rev. 2/96

## COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF MINING AND RECLAMATION

Mine Name	Rockhill Quarry
Weather	Clear 40 F

## **INSPECTION REPORT NONCOAL**

Page 1 of 1 Date <u>12/17/2004</u> On Site Times AM

PERMITTEE	TOWNSHIP				COUNTY		PERMIT NO.			
Hanson Aggregates of Pa., Inc.	East Rockhill			Bucks	7974SM1					
ADDRESS								TVD DATE		
	VIOLATIC				D TOLLOW-UP INSP. REQUIRED	LICENSE N				
1900 Sullivan Trail	HISTORY		PREVIOUS V	IOLAT	IONS: COMPLIANCE ORDER	1848		30/2005		
Easton, Pa. 18040	<u>o</u> nov's		CORRECTED		FTC ORDER CEASE ORDER C	OPERATIO	NAL S	STATUS		
610-253-4271	0CO,2		UNCORRECT	ED [	OUTSTANDING ENFORCEMENT	Active		F2		
GENERAL MINING INFORMATION: Large Noncoal Small Noncoal Complete Partial or Followup										
a. Areas-Minerals-Pit Dimensions (LW/H) – Method: Diabase Open Pit ~ 1500' (457m) x 900' (274m) x 250' (76m)										
b. Acreage (total): 103.3 (41.77ha) Bonded 103.2 Affected 103 Regraded 0 Reclaimed 0										
c. Equipment-Use & Conditions: No equipment on site										
d. Contract Miner  yes  no	e. [	3lasti	ng at Site [	⊠ ve	s no (Explain yes answer) No rec	ent blasting	a			
at a starting at										
3	F	PERFO	RMANCEST	ANDA	RDS NONCOAL					
OL- CTANDARD	1					PC or Reg.	Miel	Comp. Date		
Obs. STANDARD	PC or Reg.	Viol.	Comp. Date			PC or Reg.	V101.	Comp. Date		
X 700 Unauthorized Mining				NA	730 Concurrent Reclamation					
X 701 Signs and Markers	Noted				731 Backfilling and Grading					
NA 702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat.					
X 703 Topsoil-Rem/Sto/HnIng			14		735 Revegetation					
X 704 Effluent Standard				NA	742 Permanent Mining Cessation					
NA 706 Diversions and Conveyance	7.000 13 1000			Х	743 Haul Roads/Restoration					
X 707 Sediment Control Measures		-		Χ	745 Support Facilities		1172			
NA 708 Treatment Facilities				Х	749 General Safety					
X 709 Sedimentation Ponds				Х	753 Permit Conditions					
X 710 Discharge Structures				NA	754 Temporary Mining Cessation					
NA 711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings					
NA 712 Impoundments				Х	756 Distance Limitations-Barriers					
NA 713 Dams, Ponds-Design/Const./Maint.					757 Bench					
NA 715 Water Monitoring-Ground/Surface	i			Х	758 Permit Line Setback					
NA 717 Water Rights and Replacement			70		759 Stability Analysis					
NA 718 Water Discharge-Underground Mine					760 Post Mining Renovation					
X 723 Blasting Requirement	20000				761 Postmining Land Use					
X 727 Disposal of Solid Wastes					762 Cleanup	12.752	-			
X 728 Air Resources Protection				10.	7 OZ Gledilap					
Value (in	L			-	L	-				
COMMENTS AND DECOMMENDATION	ANO. This	4	:_!:		N and divided in the name and of NAm	C ! -4-	- I			
COMMENTS AND RECOMMENDATIONS: This partial inspection was conducted in the company of Mr. Gary Latsha										
(SMCI/DEP). The gate to the minesite was open. Mr. Tom Spellman contacted Mr. Gary Latsha to report that 500 tons of										
material was being removed as per the regulations. Material appeared to have been removed from the site.										
						63				
Minister Minter Many for the work O										
Violation History: None for the past 2	<u>years,</u>									
Person Contacted	Title			Dis	charge/Seeps ☐ yes ☒ no					
9*				Sar	mples Collected 📋 yes 🛛 no					
None					nge of Samples Collected No disch	narao				
The state of the s							D	4510		
Signature				Inve	estigator Signature	Sampler I.	.U. N	o. 4519		
¥				1	10 1 11					
Mailed				11	Bot Amice Bollinge	Emple	oyee	#608058		

<sup>.</sup> The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

District File / Permittee / Inspector