


Date 2/28/18

## EXPLOSIVES INSPECTION REPORT

(TYPE: EXPLO)

<b>Name:</b> Hanson Aggregates, LLC.	<b>Municipality/Township:</b> East Rockhill Twp	<b>License/Permit</b>	<b>Program</b>	<b>Inspected Entity</b>	<b>ENF Type</b>	<b>IRC</b>
<b>Address:</b> 7660 Imperial Way Allentown, PA 18195-1040	<b>County:</b> Bucks	BAP				
	<b>Blaster's Name:</b>	SMP 7974SM1	MIM	PF		NOVIO
<b>Telephone:</b> 610-366-4600	<b>Blasters License:</b>	BL				
	<b>Weather:</b> clear	SP				
<b>Contract Blaster:</b> Maine Drilling & Blasting, Inc.	<b>Wind Direction:</b>	PP				
<b>Address:</b>	<b>Site Name:</b> Rockhill Quarry		<b>Longitude:</b>	<b>Permit Status:</b> active		
	<b>Complaint ID:</b>		<b>Latitude:</b>	<b>Inspection Result:</b> No violations were cited.		

**Remarks:** Onsite to conduct follow-up to boulders that were blasted on 2/27/18. All boulders were drilled with 3" dia. holes. Boulders were placed into a shallow pit on the current working bench and had crushed material placed and mucked up against the boulders so as to prevent material from ejecting from the side and bottom. No seismic recordings were registered from the two seismographs that were in place for this blast. It appears that these boulders were blasted in a safe manner so as to protect the surrounding public. The boulders that were being drilled while onsite are too large to move, so rubber tire blasting mats have been brought onsite and will be used for the next boulder blast. Material will be also used again up against the sides of these boulders. It appears that these boulders blasts are being conducted in a safe manner and in compliance with the Department's regulations. No violations were cited.

<b>Person contacted (please print)</b> Darren Landis -- Peirson	<b>Title</b> Safety	<b>Times-On-Site</b> _____ to _____	<b>Page 1 of 1</b>					
<b>Blasting Inspector</b> Ross Klock	- Mailed - 	<b>ID#</b>	4	9	4	6	7	4
<b>Accompanied By</b>		<b>ID#</b>						

The responsible party signature acknowledges that he/she has read the report, including the reverse side, and that he/she was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he/she agrees with the report.

- White - District File     
  Yellow - Operator     
  Pink - Blasting Insp.     
  Goldenrod - SMCI/Other

CC: A. Bollinger, SMCI  
 G. Lohman, EGM