

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF MINING AND RECLAMATION

Mine Name Rockhill Quarry

INSPECTION REPORT
NONCOAL

Date 7/15/99

Weather Sunny ~80°F

On Site Times 9am -

PERMITTEE <u>Hanson Associates of PA Inc.</u>	TOWNSHIP <u>E. Rockhill</u>	COUNTY <u>Bucks</u>	PERMIT NO. <u>7974 Sm1</u>
ADDRESS <u>1900 Sullivan Trail Easton, PA 18040</u>	VIOLETION HISTORY <u>0 NOV'S</u> <u>0 CO'S</u> <u>9 years</u>	VIOLETIONS NOTED <input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> PREVIOUS VIOLATIONS: COMPLIANCE ORDER <input type="checkbox"/> CORRECTED <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> UNCORRECTED <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>	LICENSE NO. & EXP. DATE <u>3-00679 4/30/2000</u>
			OPERATIONAL STATUS <u>Active</u>

GENERAL MINING INFORMATION: Large Noncoal Small Noncoal Complete Partial or Followup

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: Diagonal - Open pit survey
~1500' (457m) x ~900' (274m) x ~250' (76m) - 5 levels
[103.2 (41.77 Ha)]

b. Acreage (total): Bonded 103.2 Affected ~103 (41.68 Ha) Regraded 0 Reclaimed 0

c. Equipment-Use & Conditions: Processing plant - does not appear operable.

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers) No recent blasting.

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
<input checked="" type="checkbox"/>	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat.			
	703 Topsoil-Rem/Sto/Hndng					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
<input checked="" type="checkbox"/>	706 Diversions and Conveyance				<input checked="" type="checkbox"/>	743 Haul Roads/Restoration			
<input checked="" type="checkbox"/>	707 Sediment Control Measures				<input checked="" type="checkbox"/>	745 Support Facilities			
	708 Treatment Facilities				<input checked="" type="checkbox"/>	749 General Safety			
	709 Sedimentation Ponds				<input checked="" type="checkbox"/>	753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments				<input checked="" type="checkbox"/>	756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const./Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface				<input checked="" type="checkbox"/>	758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement					761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes					762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: This inspection was conducted "as is". The site was not operating. The gate was locked and the region was quiet. The pit is water-filled. I was notified by a Hanson representative that ownership information regarding Rockhill Quarry was submitted in January of 1999 to the Department. A plan to the land on the gate should be sent to the Portville office to facilitate field inspections.

Person Contacted <u>None</u>	Title	<input checked="" type="checkbox"/> Discharge/Seeps <input type="checkbox"/> yes <input type="checkbox"/> no Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Range of Samples Collected _____ to _____
Signature <u>To be mailed</u>	Investigator Signature & I.D. No. <u>Christina Kuba</u>	<u>9556</u>