5600-FM-MR0005.7 Rev. 2/96

## COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF MINING AND RECLAMATION

|  | er Survey 700                        |            | INS                  | PECTIO     |              |   | Date <u>5</u>        | <u>//6/</u> | PM   |  |
|--|--------------------------------------|------------|----------------------|------------|--------------|---|----------------------|-------------|--|--|
| PERMITTEE HANSON AGGREGATES  |                                      |            | WNSHIP<br>, Roc.     | k HILL     |              | Bucks   | PERMIT NO. 7974 SM 1 |             |  |  |
| ADDRESS 1900 SULLIVAN TRAIL<br>EASTON DA 18040<br>610-253-4271   |                                      |            | HISTORY PREVIOUS VIC |            |              | ED   FOLLOW-UP INSP. REQUIRED   TIONS: COMPLIANCE ORDER   FTC ORDER   CEASE ORDER   O OUTSTANDING ENFORCEMENT | OPERATIONAL STATUS   |             |  |  |
| GENERAL MINING INFORMATION: Large Noncoal Small Noncoal Complete Partial or Followup  a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: DR BASE OPGN PIT  N 1500' (457m) x 900' (274m) x 250' (76 m) 5/2065  103.2 - 4/.77 Hz  b. Acreage (total): N Bonded 103.2 Affected 1/03 Regraded Reclaimed Complete PLANT  d. Contract Miner Dyes X no  e. Blasting at Site Xyes Dno (Explain yes answers) NO RECENT BLASTING |                                      |            |                      |            |              |   |                      |             |  |  |
|  |                                      |            |                      |            |              |   |                      |             |  |  |
| PERFORMANCE STANDARDS NONCOAL  |                                      |            |                      |            |              |   |                      |             |  |  |
| Obs.   | TANDARD                              | PC or Reg. | Viol.                | Comp, Date | Obs.         | STANDARD  | PC or Reg.           | Viol.       | Comp. Date                                       |  |
| i  | 700 Unauthorized Mining              |            |                      |            | NA           | 730 Concurrent Reclamation  |                      |             |  |  |
| i  | 701 Signs and Markers                |            |                      |            | 1            | 731 Backfilling and Grading   |                      |             |  |  |
|  | 702 Casing and Sealing Drilled Holes |            | 1                    |            |              | 733 Covering Coal and Acid/Toxic Mat.   |                      | -           | <del>                                     </del> |  |
|  |                                      |            | <del> </del>         |            | -   -        |   |                      |             |  |  |
| $\rightarrow$  | 703 Topsoil-Rem/Sto/HndIng           |            | <u> </u>             |            | 1            | 735 Revegetation  |                      |             |  |  |
| W  | 704 Effluent Standard                |            |                      |            | V            | 742 Permanent Mining Cessation  |                      |             |  |  |
| -1   | 706 Diversions and Conveyance        |            | 1                    |            | レ            | 743 Haul Roads/Restoration  |                      | distance.   |  |  |
| W  | 707 Sediment Control Measures        |            |                      |            | س            | 745 Support Facilities  |                      |             |  |  |
| NA   | 708 Treatment Facilities             |            | 1                    |            | V            | 749 General Safety  |                      |             |  |  |
| -  | 709 Sedimentation Ponds              |            | <b></b>              |            | V            | 753 Permit Conditions   |                      |             |  |  |
| $\rightarrow$  | 710 Discharge Structures             |            |                      |            | <b>*</b>     | 754 Temporary Mining Cessation  |                      |             |  |  |
| $\rightarrow$  |                                      |            |                      | ļ          | 7.7          |   |                      |             | <del></del>                                      |  |
|  | 711 Acid and Toxic Forming Spoil     |            | ļ                    |            |              | 755 Closing Underground Mine Openings   |                      |             |  |  |
|  | 712 Impoundments                     |            |                      |            |              | 756 Distance Limitations-Barriers   |                      |             |  |  |
| -  | 713 Dams, Ponds-Design/Const./Maint. |            | <u> </u>             |            |              | 757 Bench Development   |                      |             |  |  |
|  | 715 Water Monitoring-Ground/Surface  |            |                      |            |              | 758 Permit Line Setback   |                      | 0           |  |  |
| 11   | 717 Water Rights and Replacement     |            |                      |            |              | 759 Stability Analysis  |                      |             |  |  |
| W  | 718 Water Discharge-Underground Mine | Ŧ          |                      |            |              | 760 Post Mining Renovation  |                      |             |  |  |
| V  | 723 Blasting Requirement             |            |                      |            | 11/          | 761 Postmining Land Use   |                      |             |  |  |
| 1/   | 727 Disposal of Solid Wastes         |            |                      |            | V            | 762 Cleanup   | E STANS              |             |  |  |
|  | 728 Air Resources Protection         |            |                      |            |              |   |                      |             | <del>                                     </del> |  |
| COMMENTS AND RECOMMENDATIONS: THIS INSPECTION WAS CONSUCTED IN COMPANY OF MR. CHMIDTAN KUBA (SM.) I DENTIFICATION SIGN HAS FALLEN OUER-NEEDS TO BE RE-ERECTED (2) SITE APPRAIS MUCH<br>AS IT DID BURING LAST INSPECTION (3) WATER LEVEL IN THE PIT SEGMS<br>HIGHER, (4) SCALE HOUSE HAS BEEN REMOVED, (5) LOCK WAS MISSING ON THE  |                                      |            |                      |            |              |   |                      |             |  |  |
| COMTE, THIS SHOULD BE REPLACED AND A KEY SENT TO THE DEPARTMENT.   |                                      |            |                      |            |              |   |                      |             |  |  |
|  |                                      |            |                      |            |              |   |                      |             |  |  |
| (6) PAPERWORK FOR NAME CHANGE TO HANSON NEEDGO BY DEPARTHENT ASAP!   |                                      |            |                      |            |              |   |                      |             |  |  |
| ,  |                                      |            |                      |            |              | Discharge/Seeps   |                      |             |  |  |
|  |                                      |            |                      |            | <del>-</del> | toction to Cionatura + 1 D. No.   |                      |             |  |  |
| TO BE MAILIO   |                                      |            |                      |            |              | restigator Signature & I.D. No.   |                      |             |  |  |
| The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not   |                                      |            |                      |            |              |   |                      |             |  |  |