

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL PROTECTION  
BUREAU OF MINING AND RECLAMATION

Mine Name Rockhill Quarry  
Weather Clear - 70°F

INSPECTION REPORT  
NONCOAL

Date 11/1/99

On Site Times - PM

PERMITTEE <u>Hannon Aggregates of PA Inc.</u>	TOWNSHIP <u>E. Rockhill</u>	COUNTY <u>Bucks</u>	PERMIT NO. <u>7974 Sm 1</u>
ADDRESS <u>1900 Seltman Trail Easton, PA 18040</u> <u>610-253-4271</u>	VIOLETION HISTORY <input checked="" type="checkbox"/> NOV'S <input checked="" type="checkbox"/> CO'S <u>2 yrs</u>	VIOLETIONS NOTED <input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> PREVIOUS VIOLATIONS: COMPLIANCE ORDER <input type="checkbox"/> CORRECTED <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> UNCORRECTED <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>	LICENSE NO. & EXP. DATE <u>3-00679 4/30/2000</u> OPERATIONAL STATUS <u>Active</u>

GENERAL MINING INFORMATION: Large Noncoal  Small Noncoal \_\_\_\_\_ Complete  Partial or Followup \_\_\_\_\_

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: Discharge - Open pit quarry  
~1500' (457m) x ~900' (274m) x ~250' (76m) - 5 levels  
P103-2 (41.77 Ha)

b. Acreage (total):  Bonded 103.2 Affected ~103 (41.60 Ha) Reclaimed 0

c. Equipment-Use & Conditions: Processing plant - does not appear operable.

d. Contract Miner  yes  no e. Blasting at Site  yes  no (Explain yes answers) No recent blasting

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
<input checked="" type="checkbox"/>	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat.			
	703 Topsoil-Rem/Sto/Hndlng					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
<input checked="" type="checkbox"/>	706 Diversions and Conveyance				<input checked="" type="checkbox"/>	743 Haul Roads/Restoration			
<input checked="" type="checkbox"/>	707 Sediment Control Measures				<input checked="" type="checkbox"/>	745 Support Facilities			
	708 Treatment Facilities				<input checked="" type="checkbox"/>	749 General Safety			
	709 Sedimentation Ponds				<input checked="" type="checkbox"/>	753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments				<input checked="" type="checkbox"/>	756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const./Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement					761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes					762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: @ This inspection was conducted "side". The quarry was not operating. The site was locked and the TD area was posted. The pit is water-filled. No erosion or sedimentation problems were evident upon this inspection. Hannon is requested that a permit application 500 tons/year must be removed from the site to return active status. Please contact me at 570-621-3495 notifying when the material will have been removed.

Person Contacted <u>None</u>	Title	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
		Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
		Range of Samples Collected _____ to _____
Signature <u>To be mailed</u>	Investigator Signature & I.D. No. <u>Christina Phelan</u>	<u>ED 446538</u> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>