

Easton Road PFC
Surface Water Sample Results
Updated February 2024

Sample Location	Latitude	Longitude	Sampling Date	PFOA (ng/L)	PFOS (ng/L)
SW-01	40.33242472	-75.14523541	17-Jan-19	10.0	6.0
			19-Jun-19	11.0	6.4
SW-02	40.33232062	-75.1455768	17-Jan-19	10.0	7.0
			19-Jun-19	12.0	11.0
SW-03	40.33179435	-75.14678305	17-Jan-19	9.0	16.0
			19-Jun-19	8.9	14.0
SW-04	40.33137796	-75.14737479	17-Jan-19	10.0	6.0
			19-Jun-19	12.0	6.4
SW-05	40.3307071	-75.14933967	17-Apr-19	13.0	11.0
			19-Jun-19	11.0	6.3
SW-06	40.33047577	-75.15004521	17-Apr-19	14.0	16.0
			19-Jun-19	12.0	6.0
SW-07	40.3326224	-75.14476402	17-Apr-19	10.0	9.0
			19-Jun-19	12.0	6.3
SW-08	40.33278607	-75.14417697	17-Apr-19	13.0	7.0
			19-Jun-19	12.0	6.7
SW-09	40.33097607	-75.14746494	19-Jun-19	9.0	9.4
SW-10	40.33070873	-75.14718551	19-Jun-19	8.8	8.5
SW-11	40.32986147	-75.14653687	19-Jun-19	8.9	6.6
SW-12	40.3286643	-75.14607409	19-Jun-19	9.0	7.4
SW-13	40.3325779	-75.13435487	19-Jun-19	25.0	16.0
SW-14	40.3370873	-75.1346249	19-Jun-19	6.8	7.2
SW-15	40.33784077	-75.13250803	19-Jun-19	10.0	6.2
SW-16	40.33498211	-75.13786368	19-Jun-19	12.0	7.1
SW-17	40.35491342	-75.11021875	19-Aug-19	8.4	7.4
SW-18	40.3516466	-75.11224282	19-Aug-19	15.0	11.0
SW-19	40.35228843	-75.11428392	19-Aug-19	15.0	9.4
SW-20	40.35138905	-75.11696613	19-Aug-19	14.0	10.0
SW-21	40.35121734	-75.11755621	19-Aug-19	14.0	9.6
SW-22	40.34602313	-75.12184869	19-Aug-19	14.0	9.6
SW-23	40.34355461	-75.12465448	19-Aug-19	14.0	9.2
SW-24	40.34118024	-75.12807457	19-Aug-19	12.0	9.1
SW-01-07212022	40.35834755	-75.10624454	21-Jul-22	8.51	10.7
SW-02-07212022	40.35408799	-75.11193082	21-Jul-22	6.56	6.3
SW-03-07212022	40.35266535	-75.11351869	21-Jul-22	11.9	11.1
SW-04-07212022	40.35129174	-75.11141583	21-Jul-22	11.2	10.5
SW-05-07212022	40.35081752	-75.10841176	21-Jul-22	9.07	8.53
SW-06-07212022	40.35269806	-75.1159434	21-Jul-22	8.35	8.18
SW-07-07212022	40.3513408	-75.11678025	21-Jul-22	9.54	8.7
SW-09-07212022	40.35488923	-75.11804625	21-Jul-22	5.11	6.95

This document is intended as a summary of sample results. Complete laboratory results are available for review in the Southeast Regional Office Records Management file for the case.

Easton Road PFC
Surface Water Sample Results
Updated February 2024

Sample Location	Latitude	Longitude	Sampling Date	PFOA (ng/L)	PFOS (ng/L)
SW-1-B	40.32285	-75.16059	10-Oct-23	8.4	7.6
SW-1-C			10-Oct-23	8.5	5.6
SW-2-B	40.32715	-75.15712	10-Oct-23	8.9	7.0
SW-2-C			10-Oct-23	8.7	11.3
SW-3-C	40.32826	-75.15265	10-Oct-23	16.5	19.9
SW-4-B	40.32906	-75.15288	10-Oct-23	8.1	8.0
SW-4-C			10-Oct-23	9.3	7.5
SW-5-B	40.3307	-75.14948	10-Oct-23	8.6	7.2
SW-5-C			10-Oct-23	9.4	12.4
SW-6-C	40.32692	-75.14585	10-Oct-23	1.7 J	3.5
SW-7-B	40.33108	-75.14817	10-Oct-23	9.1	8.0
SW-7-C			10-Oct-23	8.1	9.1
SW-8-B	40.33242	-75.14519	10-Oct-23	9.9	7.1
SW-8-C			10-Oct-23	8.3	7.9
SW-9-B	40.33359	-75.14226	10-Oct-23	8.6	9.7
SW-9-C			10-Oct-23	8.5	5.5
SW-10-B	40.33443924	-75.13956043	10-Oct-23	8.4	8.4
SW-10-C			10-Oct-23	8.4	7.9
SW-11-C	40.33331686	-75.13488173	11-Oct-23	7.4	8.5
SW-12-B	40.33618	-75.13497	11-Oct-23	7.8	6.8
SW-12-C			11-Oct-23	8.2	6.7
SW-13-B	40.33895	-75.13149	11-Oct-23	8.7	8.0
SW-13-C			11-Oct-23	7.8	7.8
SW-14-C	40.3403	-75.12275	11-Oct-23	3.0	2.2
SW-14_1-C	40.34002	-75.12039	11-Oct-23	ND	1.3 J
SW-15-B	40.34287	-75.12557	11-Oct-23	7.4	9.7
SW-15-C			11-Oct-23	8.5	8.5
SW-16-B	40.34763	-75.11942	11-Oct-23	7.3	6.6
SW-16-C			11-Oct-23	8.9	8.7
SW-17-C	40.3480224	-75.11920077	11-Oct-23	2.3	3.8
SW-18-B	40.35115	-75.11711	11-Oct-23	7.4	7.4
SW-18-C			11-Oct-23	8.3	10.5
SW-19-B	40.3521	-75.11456	11-Oct-23	8.9	7.9
SW-19-C			11-Oct-23	8.4	14.1
SW-20-C	40.35427	-75.11233	11-Oct-23	6.0	7.4
SW-21-B	40.35143	-75.11177	11-Oct-23	9.7	11.8
SW-21-C			11-Oct-23	10.3	10.0
SW-22-B	40.35102	-75.11088	11-Oct-23	9.2	12.3
SW-22-C			11-Oct-23	10.3	8.1

This document is intended as a summary of sample results. Complete laboratory results are available for review in the Southeast Regional Office Records Management file for the case.