

October 3, 2017

Mr. Matthew Gordon Sunoco Logistics, L.P. 535 Fritztown Road Sinking Spring, Pennsylvania 19608

Re: Hydrogeological Re-Evaluation Report

Aughwick Creek Horizontal Directional Drill Location (S2-0153)

Application No. E31-234

Shirley Township, Huntingdon County

Dear Mr. Gordon:

DEP is requesting more information related to the HDD Analysis for the S2-0153, E31-234, posted on the DEP Mariner East II pipeline portal webpage on September 8, 2017.

- 1. No cross-sections or profiles of the HDD's have been provided. Consequently, it is not possible to determine if SPLP has satisfied the requirements of paragraphs 4 and 5 of the EHB corrected and stipulated order (2017-009-L)
- 2. No analysis or discussion of geologic strength or overburden strength at profile depth has been provided as per the requirements of paragraph 4 ii of the EHB corrected and stipulated order (2017-009-L)
- 3. Published geologic data and site-specific drill logs indicate the presence of both carbonate lithologies and voids however, contrary to paragraph 4 iii and iv of the EHB corrected and stipulated order (2017-009-L) no geophysical surveys or explanation as to why they were not performed has been provided.
- 4. No analysis or discussion of pipe stress radius has been provided as per the requirement set forth in paragraph 4 ii of the EHB corrected and stipulated order (2017-009-L)

Upon receipt, DEP will post requested additional information on the DEP pipeline portal webpage for public comment. The public will have 5 additional business days from the date of posting on the website to provide DEP any additional comment.

Sincerely,

Scott R. Williamson

Program Manager

Waterways & Wetlands Program

cc: Douglass J. Hess, P.G., RETTEW

Ethan E. Prout, P.G., RETTEW

Christopher T. Brixius, P.G., RETTEW