Version: 1.1 Effective Date: Jul-20-2015 Previous Date: Feb-04-2015



SAFETY DATA SHEET STEAMATE* LSA1791

1. Identification

Product identifier STEAMATE LSA1791

Other means of identification None.

Recommended use Steam condensate treatment.

Recommended restrictions None known.

Company/undertaking identification

GE Betz, Inc. 4636 Somerton Road Trevose, PA 19053 T 215 355 3300, F 215 953 5524

Emergency telephone

(800) 877 1940

2. Hazard(s) identification

Physical hazards Flammable liquids Category 3 Acute toxicity, oral Health hazards Category 4 Acute toxicity, dermal Category 3 Acute toxicity, inhalation Category 3 Skin corrosion/irritation Category 1B Serious eye damage/eye irritation Category 1 Reproductive toxicity Category 2

> Category 3 respiratory tract irritation Specific target organ toxicity, single exposure

Aspiration hazard Category 1

Not classified. OSHA defined hazards

Label elements



Signal word Danger

Flammable liquid and vapor. Harmful if swallowed. May be fatal if swallowed and enters airways. Toxic Hazard statement in contact with skin. Causes severe skin burns and eye damage. Causes serious eye damage. Toxic if

inhaled. May cause respiratory irritation. Suspected of damaging fertility or the unborn child.

Precautionary statement Prevention

Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Keep away from heat/sparks/open flames/hot surfaces. - No smoking. Keep container tightly closed. Ground/bond container and receiving equipment. Use explosion-proof electrical/ventilating/lighting// equipment. Use only non-sparking tools. Take precautionary measures against static discharge. Do not breathe mist or vapor. Wash thoroughly after handling. Do not eat, drink or smoke when using this product. Use only outdoors or in a well-ventilated area. Wear protective gloves/protective clothing/eye protection/face protection.

Response If swallowed: Immediately call a poison center/doctor/. If swallowed: Rinse mouth. Do NOT induce

vomiting. If on skin (or hair): Take off immediately all contaminated clothing. Rinse skin with water/shower. If inhaled: Remove person to fresh air and keep comfortable for breathing. If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a poison center/doctor/. Specific treatment (see on this label). Do NOT induce vomiting. Take off immediately all contaminated clothing and wash it before reuse. In case

of fire: Use to extinguish.

Storage Store in a well-ventilated place. Keep container tightly closed. Store in a well-ventilated place. Keep

cool. Store locked up.

Disposal Dispose of contents/container to .

Hazard(s) not otherwise classified

(HNOC)

None known.

Supplemental information None.

3. Composition/information on ingredients

Mixtures

Components	CAS#	Percent	
Dimethylaminoethanol (DMAE)	108-01-0	60 - 80	
Cyclohexylamine	108-91-8	10 - 20	

^{*}Designates that a specific chemical identity and/or percentage of composition has been withheld as a trade secret.

Composition comments

Information for specific product ingredients as required by the U.S. OSHA HAZARD COMMUNICATION STANDARD is listed. Refer to additional sections of this SDS for our assessment of the potential hazards of this formulation.

4. First-aid measures

Inhalation

Remove victim to fresh air and keep at rest in a position comfortable for breathing. Oxygen or artificial respiration if needed. Do not use mouth-to-mouth method if victim inhaled the substance. Induce artificial respiration with the aid of a pocket mask equipped with a one-way valve or other proper respiratory medical device. Call a POISON CENTER or doctor/physician.

Skin contact

Take off immediately all contaminated clothing. Rinse skin with water/shower. Call a physician or poison control center immediately. Chemical burns must be treated by a physician. Wash contaminated clothing before reuse.

Eye contact

Immediately flush eyes with plenty of low-pressure water for at least 20 minutes while removing contact lenses. Continue rinsing. Call a physician or poison control center immediately.

Ingestion

Call a physician or poison control center immediately. Rinse mouth. Do not induce vomiting. If vomiting occurs, keep head low so that stomach content doesn't get into the lungs.

Most important

symptoms/effects, acute and

delayed

Burning pain and severe corrosive skin damage. Aspiration may cause pulmonary edema and pneumonitis. Causes serious eye damage. Symptoms may include stinging, tearing, redness, swelling, and blurred vision. Permanent eye damage including blindness could result. May cause respiratory irritation

Indication of immediate medical attention and special treatment needed

Provide general supportive measures and treat symptomatically. Thermal burns: Flush with water immediately. While flushing, remove clothes which do not adhere to affected area. Call an ambulance. Continue flushing during transport to hospital. Chemical burns: Flush with water immediately. While flushing, remove clothes which do not adhere to affected area. Call an ambulance. Continue flushing during transport to hospital. Keep victim warm. Keep victim under observation. Symptoms may be delayed.

General information

Take off immediately all contaminated clothing. IF exposed or concerned: Get medical advice/attention. If you feel unwell, seek medical advice (show the label where possible). Ensure that medical personnel are aware of the material(s) involved, and take precautions to protect themselves. Show this safety data sheet to the doctor in attendance. Wash contaminated clothing before reuse.

5. Fire-fighting measures

Suitable extinguishing media Unsuitable extinguishing media

Specific hazards arising from the

chemical

 ${\bf Alcohol\ resistant\ foam.\ Water\ fog.\ Dry\ chemical\ powder.\ Carbon\ dioxide\ (CO2).}$

Do not use water jet as an extinguisher, as this will spread the fire.

Vapors may form explosive mixtures with air. Vapors may travel considerable distance to a source of ignition and flash back. During fire, gases hazardous to health may be formed.

Special protective equipment and precautions for firefighters

precautions for firefighters
Fire fighting

Self-contained breathing apparatus and full protective clothing must be worn in case of fire.

equipment/instructions

In case of fire and/or explosion do not breathe fumes. Move containers from fire area if you can do so without risk.

Material name: STEAMATE* LSA1791

Specific methodsUse standard firefighting procedures and consider the hazards of other involved materials.

General fire hazards Flammable liquid and vapor.

6. Accidental release measures

Personal precautions, protective equipment and emergency procedures

Keep unnecessary personnel away. Keep people away from and upwind of spill/leak. Keep out of low areas. Eliminate all ignition sources (no smoking, flares, sparks, or flames in immediate area). Wear appropriate protective equipment and clothing during clean-up. Do not breathe mist or vapor. Do not touch damaged containers or spilled material unless wearing appropriate protective clothing. Ventilate closed spaces before entering them. Local authorities should be advised if significant spillages cannot be contained. For personal protection, see section 8 of the SDS.

Methods and materials for containment and cleaning up

Eliminate all ignition sources (no smoking, flares, sparks, or flames in immediate area). Take precautionary measures against static discharge. Use only non-sparking tools. Keep combustibles (wood, paper, oil, etc.) away from spilled material.

Large Spills: Stop the flow of material, if this is without risk. Use water spray to reduce vapors or divert vapor cloud drift. Dike the spilled material, where this is possible. Cover with plastic sheet to prevent spreading. Use a non-combustible material like vermiculite, sand or earth to soak up the product and place into a container for later disposal. Prevent entry into waterways, sewer, basements or confined areas. Following product recovery, flush area with water.

Small Spills: Absorb with earth, sand or other non-combustible material and transfer to containers for later disposal. Clean surface thoroughly to remove residual contamination.

Never return spills to original containers for re-use. For waste disposal, see section 13 of the SDS.

Environmental precautions

Avoid discharge into drains, water courses or onto the ground.

7. Handling and storage

Precautions for safe handling

Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Do not handle, store or open near an open flame, sources of heat or sources of ignition. Protect material from direct sunlight. Explosion-proof general and local exhaust ventilation. Take precautionary measures against static discharges. All equipment used when handling the product must be grounded. Use non-sparking tools and explosion-proof equipment. Do not breathe mist or vapor. Do not get in eyes, on skin, or on clothing. Avoid prolonged exposure. Do not taste or swallow. When using, do not eat, drink or smoke. Pregnant or breastfeeding women must not handle this product. Should be handled in closed systems, if possible. Wear appropriate personal protective equipment. Wash hands thoroughly after handling. Observe good industrial hygiene practices. Wash contaminated clothing before reuse.

Conditions for safe storage, including any incompatibilities

Store locked up. Keep away from heat, sparks and open flame. Prevent electrostatic charge build-up by using common bonding and grounding techniques. Store in a cool, dry place out of direct sunlight. Store in original tightly closed container. Store in a well-ventilated place. Keep in an area equipped with sprinklers. Store away from incompatible materials (see Section 10 of the SDS).

8. Exposure controls/personal protection

Occupational exposure limits

US. ACGIH Threshold Limit Values

Components	Туре	Value	
Cyclohexylamine (CAS 108-91-8)	TWA	10 ppm	
US. NIOSH: Pocket Guide to Chem	ical Hazards		
Components	Туре	Value	
Cyclohexylamine (CAS	TWA	40 mg/m3	
108-91-8)		10 ppm	

Biological limit values

No biological exposure limits noted for the ingredient(s).

Appropriate engineering controls

Explosion-proof general and local exhaust ventilation. Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation, or other engineering controls to maintain airborne levels below recommended exposure limits. If exposure limits have not been established, maintain airborne levels to an acceptable level. Eye wash facilities and emergency shower must be available when handling this product.

Individual protection measures, such as personal protective equipment

Eye/face protection Splash proof chemical goggles. Face shield.

Version number: 1.1

Material name: STEAMATE* LSA1791 Page: 3 / 9

Skin protection

Hand protection Wear appropriate chemical resistant gloves. The choice of an appropriate glove does not only depend

on its material but also on other quality features and is different from one producer to the other. Glove

selection must take into account any solvents and other hazards present.

Other Wear appropriate chemical resistant clothing. Use of an impervious apron is recommended.

Respiratory protection Chemical respirator with organic vapor cartridge and full facepiece. A RESPIRATORY PROTECTION

PROGRAM THAT MEETS OSHA'S 29 CFR 1910.134 AND ANSI Z88.2 REQUIREMENTS MUST BE FOLLOWED

WHENEVER WORKPLACE CONDITIONS WARRANT A RESPIRATOR'S USE.

Thermal hazards Wear appropriate thermal protective clothing, when necessary.

General hygiene considerations When using, do not eat, drink or smoke. Always observe good personal hygiene measures, such as

washing after handling the material and before eating, drinking, and/or smoking. Routinely wash work

clothing and protective equipment to remove contaminants.

9. Physical and chemical properties

Appearance

Color Colorless to light yellow

Physical state Liquid

OdorStrong amineOdor thresholdNot available.

pH (concentrated product) 12.6

pH in aqueous solution 11.8 (5% SOL.)

Melting point/freezing point <-22 °F (<-30 °C)

Initial boiling point and boiling Not available.

range

Flash point 120 °F (49 °C) P-M(CC)

Evaporation rate < 1 (Ether = 1)
Flammability (solid, gas) Not available.

Upper/lower flammability or explosive limits

Flammability limit - lower (%) Not available.
Flammability limit - upper Not available.

(%)

Explosive limit - lower (%)Not available.Explosive limit - upper (%)Not available.Vapor pressure< 11 mm HgVapor pressure temp.70 °F (21 °C)Vapor density> 1 (Air = 1)Relative density0.91

Relative density temperature 70 °F (21 °C)

Solubility(ies)

Solubility (water) 100 %

Partition coefficient Not available.

(n-octanol/water)

Auto-ignition temperature Not available.

Decomposition temperature Not available.

 $\begin{tabular}{lll} \mbox{Viscosity} & 15 \mbox{ cps} \\ \mbox{Viscosity temperature} & 70 \mbox{ °F (21 °C)} \\ \end{tabular}$

Other information

Percent volatile 90 (Estimated)

Pour point <-22 °F (<-30 °C)

Specific gravity 0.91

Material name: STEAMATE* LSA1791

10. Stability and reactivity

ReactivityThe product is stable and non-reactive under normal conditions of use, storage and transport.

Chemical stability Material is stable under normal conditions.

Possibility of hazardous reactions Hazardous polymerization does not occur.

Conditions to avoid Avoid heat, sparks, open flames and other ignition sources. Avoid temperatures exceeding the flash

point. Contact with incompatible materials.

Incompatible materials Aluminum. Peroxides. Phenols.

Hazardous decomposition

products

Ammonia, oxides of carbon and nitrogen evolved in fire.

11. Toxicological information

Information on likely routes of exposure

Inhalation Toxic if inhaled.

Skin contact Toxic in contact with skin. Causes severe skin burns.

Eye contact Causes serious eye damage.

Ingestion Causes digestive tract burns. Harmful if swallowed. Droplets of the product aspirated into the lungs

through ingestion or vomiting may cause a serious chemical pneumonia.

Symptoms related to the physical, chemical and toxicological

characteristics

Burning pain and severe corrosive skin damage. Aspiration may cause pulmonary edema and pneumonitis. Causes serious eye damage. Symptoms may include stinging, tearing, redness, swelling, and blurred vision. Permanent eye damage including blindness could result. May cause respiratory irritation.

Information on toxicological effects

Acute toxicity May be fatal if swallowed and enters airways. Toxic if inhaled. Toxic in contact with skin. May cause

respiratory irritation.

Product Species Test Results STEAMATE LSA1791 (CAS Mixture) Acute Dermal Rabbit 868 mg/kg, (Calculated according to GHS LD50 additivity formula (Category 3)) Inhalation LC50 Rat 8.15 mg/l, 4 Hours, (Calculated according to GHS additivity formula (Category 3)) Oral LD50 Rat 625 mg/kg, (Calculated according to GHS additivity formula (Category 4)) Components **Species Test Results** Cyclohexylamine (CAS 108-91-8) Acute Dermal LD50 Rabbit 277 mg/kg Oral 156 mg/kg LD50 Rat Dimethylaminoethanol (DMAE) (CAS 108-01-0) Acute Dermal LD50 Rabbit 1220 mg/kg Inhalation LC50 Rat 6.1 mg/l, 4 Hour Oral LD50 1210 mg/kg Rat

Skin corrosion/irritation Causes severe skin burns and eye damage.

Material name: STEAMATE* LSA1791 Page: 5 / 9

^{*} Estimates for product may be based on additional component data not shown.

Causes serious eve damage. Serious eye damage/eye irritation

Respiratory or skin sensitization

Not available. Respiratory sensitization

Skin sensitization This product is not expected to cause skin sensitization.

No data available to indicate product or any components present at greater than 0.1% are mutagenic or Germ cell mutagenicity

genotoxic.

This product is not considered to be a carcinogen by IARC, ACGIH, NTP, or OSHA. Carcinogenicity

OSHA Specifically Regulated Substances (29 CFR 1910.1001-1050)

Not listed.

Suspected of damaging fertility or the unborn child. Reproductive toxicity

Specific target organ toxicity -

single exposure

May cause respiratory irritation.

Specific target organ toxicity -

repeated exposure Aspiration hazard

Not classified.

May be fatal if swallowed and enters airways.

Chronic effects Prolonged inhalation may be harmful.

12. Ecological information

The product is not classified as environmentally hazardous. However, this does not exclude the **Ecotoxicity**

possibility that large or frequent spills can have a harmful or damaging effect on the environment.

Product		Species	Test Results
STEAMATE LSA1791 (CA	AS Mixture)		
	LC50	Fathead Minnow	13.2 mg/l, Static Renewal Bioassay, 96 hour, (pH adjusted)
	NOEL	Fathead Minnow	10 mg/l, Static Renewal Bioassay, 96 hour, (pH adjusted)
Aquatic			
Crustacea	LC50	Daphnia magna	13.2 mg/l, Static Renewal Bioassay, 96 hour, (pH adjusted)
	NOEL	Daphnia magna	10 mg/l, Static Renewal Bioassay, 96 hour, (pH adjusted)

^{*} Estimates for product may be based on additional component data not shown.

No data available. **Bioaccumulative potential**

Partition coefficient n-octanol / water (log Kow)

Cyclohexylamine 1.49

No data available. Mobility in soil

No other adverse environmental effects (e.g. ozone depletion, photochemical ozone creation potential, Other adverse effects

endocrine disruption, global warming potential) are expected from this component.

The product is not classified as environmentally hazardous. However, this does not exclude the **Environmental fate**

possibility that large or frequent spills can have a harmful or damaging effect on the environment.

Persistence and degradability

No data is available on the degradability of this product.

13. Disposal considerations

Collect and reclaim or dispose in sealed containers at licensed waste disposal site. Incinerate the **Disposal instructions**

material under controlled conditions in an approved incinerator. Do not incinerate sealed containers. If discarded, this product is considered a RCRA ignitable waste, D001. Dispose of contents/container in

accordance with local/regional/national/international regulations.

Dispose in accordance with all applicable regulations. Local disposal regulations Hazardous waste code

D001: Waste Flammable material with a flash point <140 F

D002: Waste Corrosive material [pH <=2 or =>12.5, or corrosive to steel]

The waste code should be assigned in discussion between the user, the producer and the waste disposal

Waste from residues / unused

products

Dispose of in accordance with local regulations. Empty containers or liners may retain some product residues. This material and its container must be disposed of in a safe manner (see: Disposal

instructions).

Material name: STEAMATE* LSA1791

Version number: 1.1

Page: 6 / 9

Contaminated packaging

Empty containers should be taken to an approved waste handling site for recycling or disposal. Since emptied containers may retain product residue, follow label warnings even after container is emptied.

14. Transport information

DOT

UN number UN2734

UN proper shipping name AMINES, LIQUID, CORROSIVE, FLAMMABLE, N.O.S. (DIMETHYLAMINOETHANOL, CYCLOHEXYLAMINE RQ =

670 LBS)

Transport hazard class(es)

Class 8
Subsidiary risk 3, 6.1
Packing group

Special precautions for user Read safety instructions, SDS and emergency procedures before handling.

ERG number 132

Some containers may be exempt from Dangerous Goods/Hazmat Transport Regulations, please check BOL for exact container

classification.

IATA

UN number Not available.

UN proper shipping name Transport hazard class(es) DO NOT SHIP. NOT CLASSIFIED. CALL PRODUCT COMPLIANCE.

Class Not available.

Subsidiary risk Packing group Not applicable.

Environmental hazards No

Special precautions for user Read safety instructions, SDS and emergency procedures before handling.

IMDG

UN number Not available.

UN proper shipping nameDO NOT SHIP. NOT CLASSIFIED. CALL PRODUCT COMPLIANCE. **Transport hazard class(es)**

Class Not available.

Subsidiary risk

Packing group Not applicable.

Environmental hazards

Marine pollutant No.

EmS Not available.

Special precautions for user Read safety instructions, SDS and emergency procedures before handling.

DOT



15. Regulatory information

US federal regulationsThis product is a "Hazardous Chemical" as defined by the OSHA Hazard Communication Standard, 29

CFR 1910.1200.

All components are on the U.S. EPA TSCA Inventory List.

TSCA Section 12(b) Export Notification (40 CFR 707, Subpt. D)

Not regulated.

CERCLA Hazardous Substance List (40 CFR 302.4)

Cyclohexylamine (CAS 108-91-8) Listed.

SARA 304 Emergency release notification

Cyclohexylamine (CAS 108-91-8) 10000 LBS

OSHA Specifically Regulated Substances (29 CFR 1910.1001-1050)

Not listed.

Material name: STEAMATE* LSA1791 Page: 7 / 9

Superfund Amendments and Reauthorization Act of 1986 (SARA)

Hazard categories Immediate Hazard - Yes

Delayed Hazard - Yes Fire Hazard - Yes Pressure Hazard - No Reactivity Hazard - No

SARA 302 Extremely hazardous substance

Chemical name	CAS number	Reportable quantity	Threshold planning quantity	Threshold planning quantity, lower value	Threshold planning quantity, upper value
Cyclohexylamine	108-91-8	10000	10000 lbs		

SARA 311/312 Hazardous

No

chemical

SARA 313 (TRI reporting)

Not regulated.

Other federal regulations

Clean Air Act (CAA) Section 112 Hazardous Air Pollutants (HAPs) List

Not regulated.

Clean Air Act (CAA) Section 112(r) Accidental Release Prevention (40 CFR 68.130)

Cyclohexylamine (CAS 108-91-8)

Safe Drinking Water Act

Not regulated.

(SDWA)

Inventory status

Country(s) or region	Inventory name	On inventory (yes/no)*
Canada	Domestic Substances List (DSL)	No
Canada	Non-Domestic Substances List (NDSL)	Yes
United States & Puerto Rico	Toxic Substances Control Act (TSCA) Inventory	Yes

^{*}A "Yes" indicates that all components of this product comply with the inventory requirements administered by the governing country(s) A "No" indicates that one or more components of the product are not listed or exempt from listing on the inventory administered by the governing country(s).

US state regulations

US - Massachusetts RTK - Substance List

Cyclohexylamine (CAS 108-91-8)

Dimethylaminoethanol (DMAE) (CAS 108-01-0)

US - Pennsylvania RTK - Hazardous Substances

Cyclohexylamine (CAS 108-91-8)

Dimethylaminoethanol (DMAE) (CAS 108-01-0)

US - Rhode Island RTK

Cyclohexylamine (CAS 108-91-8)

US. California Controlled Substances. CA Department of Justice (California Health and Safety Code Section 11100)

Not listed.

US. New Jersey Worker and Community Right-to-Know Act

Cyclohexylamine (CAS 108-91-8)

Dimethylaminoethanol (DMAE) (CAS 108-01-0)

US. Pennsylvania Worker and Community Right-to-Know Law

Cyclohexylamine (CAS 108-91-8)

Dimethylaminoethanol (DMAE) (CAS 108-01-0)

US. California Proposition 65

WARNING: This product contains a chemical known to the State of California to cause cancer.

US - California Proposition 65 - CRT: Listed date/Carcinogenic substance

Aniline (CAS 62-53-3) Listed: January 1, 1990

US - California Proposition 65 - CRT: Listed date/Developmental toxin

No ingredient listed.

US - California Proposition 65 - CRT: Listed date/Female reproductive toxin

No ingredient listed.

US - California Proposition 65 - CRT: Listed date/Male reproductive toxin

No ingredient listed.

Material name: STEAMATE* LSA1791 Page: 8 / 9

16. Other information, including date of preparation or last revision

Issue dateFeb-04-2015Revision dateJul-20-2015

Version # 1.1

List of abbreviations

CAS: Chemical Abstract Service Registration Number

TSRN indicates a Trade Secret Registry Number is used in place of the CAS number.

ACGIH: American Conference of Governmental Industrial Hygienists

NOEL: No Observed Effect Level STEL: Short Term Exposure Limit LC50: Lethal Concentration, 50% TWA: Time Weighted Average BOD: Biochemical Oxygen Demand COD: Chemical Oxygen Demand TOC: Total Organic Carbon

IATA: International Air Transport Association

IMDG: International Maritime Dangerous Goods Code

LD50: Lethal Dose, 50%

NFPA: National Fire Protection Association

References: No data available

Disclaimer The information provided in this Safety Data Sheet is correct to the best of our knowledge, information

and belief at the date of its publication. The information given is designed only as a guidance for safe handling, use, processing, storage, transportation, disposal and release and is not to be considered a warranty or quality specification. The information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process, unless specified in the text. The information in the sheet was written based on the best knowledge and

experience currently available.

Revision Information Physical & Chemical Properties: Multiple Properties

Toxicological Information: Toxicological Data

Transport Information: Material Transportation Information

Other information, including date of preparation or last revision: Prepared by

GHS: Classification

Prepared by This SDS has been prepared by GE Water & Process Technologies Regulatory Department

(1-215-355-3300).

Material name: STEAMATE* LSA1791 Page: 9 / 9

^{*} Trademark of General Electric Company. May be registered in one or more countries.