

October 6, 2017

Mr. Matthew Gordon
Sunoco Logistics, L.P.
535 Fritztown Road
Sinking Spring, Pennsylvania 19608

Re: Hydrogeological Re-Evaluation Report
Eagleview Boulevard, Horizontal Directional Drill Location (S3-0321)
PA DEP Permit No. E15-862
Uwchlan Township, Chester County


Dear Mr. Gordon:

DEP is requesting more information related to the HDD Analysis for the Eagleview Boulevard, Horizontal Directional Drill Location (S3-0321), DEP Permit No. E15-862, posted on the DEP Mariner East II pipeline portal webpage on September 15, 2017.

1. Provide confirmation that you identified all water supplies within 450 feet from the HDD alignment.
 - a. Confirm that you provided the proper and adequate notice to all property owners within 450 feet from the HDD alignment and asked for their water supply information.
 - b. Provide all documentation from item 1.a.
 - c. Provide the property owners' responses to the notifications.
2. Provide discussion and consideration of potential risks to private water supplies.

If you have any questions regarding this matter, please contact me at 484.250.5174, or by email at drocco@pa.gov.

Sincerely,



Domenic Rocco, P.E.
Program Manager
Waterways & Wetlands Program

cc: Mr. Waldrop, P.G., GES
Chester County Conservation District
Re 30