

**From:** [Nick Mobile](#)  
**To:** [EP, SERO ECB](#)  
**Subject:** [External] Concerns About Bishop Tube  
**Date:** Thursday, January 27, 2022 1:39:32 PM

---

***ATTENTION:** This email message is from an external sender. Do not open links or attachments from unknown sources. To report suspicious email, forward the message as an attachment to [CWOPA\\_SPAM@pa.gov](mailto:CWOPA_SPAM@pa.gov).*

To whom it may concern,

- The DEP must inform the community how technical and management challenges to remediation will be met.
- Prior clean up attempts at Bishop Tube were unsuccessful. Better management techniques and ongoing performance assessment should be outlined within the plan.
- The community needs clarification concerning areas such as duration of remediations efforts, potential for production of additional toxic compounds, and protection of the Little Valley Creek.
- The DEP must provide the public additional information on how it intends to evaluate and address the presence of DNAPL within the deep bedrock aquifer.
- The DEP should inform the public, regarding how remediation will be financed and whether this may limit remedial activities.

Nick Mobile  
42 Village Way, Malvern, PA 19355