CHAPTER 302 ADMINISTRATION OF THE WATER AND WASTEWATER SYSTEMS OPERATORS' CERTIFICATION PROGRAM

DUTIES OF OWNERS AND OPERATORS

Duties of Owners

Ch. 302 Citation	Description	Example
302.104(a)	An unauthorized person made process control decisions at a wastewater facility without proper certification	Uncertified/not properly certified owner or owner's representative shall contact the available operator, shall follow direction or an SOP, or autocontrol by a PLC/SCADA.

Ch. 302 Citation	Description	
302.1202	Owner shall comply with the Act or Chapter 302 regulations	
302.1202(a)(1)	Owner shall comply with permit conditions and requirements applicable to the operation of the system.	
302.1202(a)(2)	Owner shall ensure process control decisions were made by available operators with a valid, appropriate certificate. i.e. operator available – onsite and for sufficient time, able to be contacted with correct contact info given, or an approved and adequate SOP, or a PLC/SCADA system set up for automatic control. Owner shall employ an operator with a valid, appropriate certificate. Owner shall approve a circuit rider's Specific Management Plan.	
302.1202(a)(3)	Owner shall post the name and contact information of available operator(s).	
302.1202(a)(4)	Owner shall take appropriate action in a timely manner in response to the Operator Report to Owner.	
302.1202(a)(5)	Owner shall provide a copy of current, relevant permits to all available operators. Owner shall submit a written request to DEP to provide the current permits to the designated available operator.	
302.1202(b)(6)	Owner shall designate an operator in responsible charge (OIRC) when the owner choses to develop and use SOPs.	
302.1202(c)	Owner shall notify DEP within 10 days of when the available operator(s) changed. https://www.logiforms.com/formdata/user_forms/23785_4145344/77494/	
302.1203(c)	Owner shall have a process control plan when required by DEP.	

CHAPTER 302 ADMINISTRATION OF THE WATER AND WASTEWATER SYSTEMS OPERATORS' CERTIFICATION PROGRAM

DUTIES OF OWNERS AND OPERATORS

Duties of Owners (continued)

Ch. 302 Citation	Description	
302.1204(b)	Owner shall ensure the 4 requirements for SOPs are met, if in use: 1. name of OIRC, 2. who may use the SOP, 3. processes covered by SOP or whom to contact if not covered, 4. trigger parameters and actions to be taken.	
302.1204(c)	Owner shall approve and date the SOP, and have the SOP available at the system.	
302.1205	Owner shall have the necessary number of available operators [1]; or more if required by DEP.	
302.1206(a)	Owner shall notify DEP within 10 days of when the operator in responsible charge (OIRC) changed. Owner shall notify the OIRC of this designation in writing.	
302.1206(b)	Owner shall provide the required information (name, client ID, cert. #) about an OIRC upon request by DEP.	
302.1206(c)	Owner shall ensure that the operator designated as the OIRC holds a valid, appropriate certificate.	
302.1207(d)	Owner shall notify DEP within 10 days of when a circuit rider is employed to operate the system.	
302.1207(g)	Owner shall approve through signature the circuit rider' s specific management plan.	

CHAPTER 302 ADMINISTRATION OF THE WATER AND WASTEWATER SYSTEMS OPERATORS' CERTIFICATION PROGRAM

DUTIES OF OWNERS AND OPERATORS

Duties of Operators

Ch. 302 Citation	Description	Examples
302.104(a)	An unauthorized person made process control decisions at a wastewater facility without proper certification	Uncertified/not properly certified person shall contact the available operator, shall follow direction or an SOP, or autocontrol by a PLC/SCADA.

Ch. 302 Citation	Description			
Operator sl	Operator shall comply with the Act or Chapter 302 regulations			
302.1201(a)	Certified operator / available operator shall comply with the act, this chapter, and other law or rules and regulations applicable to the operation of systems. Certified operator shall provide suitable operation and maintenance using available resources. [consider report per 302.1201(c) & owner's response per 302.1202(a)(4)]			
302.1201(c)	Certified operator shall report to the owner known violations or conditions that may be or are causing violations. [when resources are needed or lacking]			
302.1201(c)	Certified operator shall provide an <i>Operator Report to the Owner</i> including the 6 requirements (name, date, nature of violation or condition, suspected cause including lack of needed resources, degree of severity, action or measures associated with process control to prevent or eliminate violation/condition). [template available]			
302.1203(a)	Available operator shall make all process control decisions. [by being available onsite or remotely, by using approved SOPs, or by using a PLC/SCADA system to direct the actions of certified and noncertified operators]			
302.1204(c)	Operator in responsible charge (OIRC) shall approve and date SOPs.			
302.1207(e)	Circuit rider shall develop and submit a general work plan [work contract or template] to the owner, that includes the 4 requirements: 1. business name/location, 2. inventory of circuit rider's facilities/systems, 3. class & subclass of each system, 4. number of estimated hours per week and visits per month at each. [template available]			
302.1207(f)	Circuit rider shall develop and submit a system specific management plan that includes the 4 requirements: 1. name, contact info & certificates for available operators, 2. SOP & process control plan, 3. emergency contact info, 4. estimate of emergency response time. [template available]			