

Exhibit A: Monitoring well and surface water sampling locations.




Exhibit B: EQT Phoenix Pad S site overview. Photo taken 5/31/13.



Exhibit C: View of Impoundment 2 looking SE. West Seeps impacted area in foreground. Photo taken 8/2/12.



Exhibit D: Water quality Danzer 1 spring.




Exhibit E: Water quality lower west seeps.




Exhibit F: Groundwater chloride concentrations in mg/L- May 30, 2012.

Secondary Maximum Contaminant Level (SMCL) is 250 mg/L.




Exhibit G: Groundwater chloride concentrations in mg/L - June 25, 2014, Secondary Maximum Contaminant Level (SMCL) is 250 mg/L.




Exhibit H: Chloride concentrations versus time in select wells.

