

Commonwealth of Pennsylvania

DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF SURFACE MINE RECLAMATION
INSPECTION
REPORT

Mine No. 733-5
Drainage Permit No. 79745M1
Mine Inspection No. 54
Reinspection No. 2-83

Company <u>GENERAL CRUSHED STONE</u>		Mine Location: County <u>BUCKS</u>	Township <u>E ROCKHILL</u>
Mining Permit Acres Affected <u>95</u>		Drainage Permit Acres Affected	
Status of Operation: Active <u>X</u>	Inactive	Not Started	

1. Is this operation in compliance with the Safety Rules and Regulations? YES X NO _____ NOTED _____
2. Is this mine operating in compliance with the conditions of the mining permit? YES X NO _____ NOTED _____
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES X NO _____ NOTED _____

REMARKS AND RECOMMENDATIONS: FRONT END LOADER LOADING FROM STOCK PILE

WATER IN PIT SUMP CHECK - 45' DEEP -

I FOUND NO STE PROBLEMS

Company Official Contacted <u>Judy W Smergart</u>	Title <u>Dispatcher</u>
Mine Inspector <u>Jonas Carpenter</u>	Inspection Date <u>4-28-83</u>

INSPECTORS' RECOMMENDATIONS TO BUREAU: