

Commonwealth of Penns.

DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF SURFACE MINE RECLAMATION
INSPECTION
REPORT

Mini. : No. 733-5
Drainage Permit No. 7974SM1
Mine Inspection No. 54
Reinspection No. 2-81

Company <u>General Crushed Stone Co</u>		Mine Location: County <u>BECKS</u>	Township <u>E. ROCKHILL.</u>
Mining Permit Acres Affected <u>70</u>		Drainage Permit Acres Affected <u>70</u>	
Status of Operation: Active <input checked="" type="checkbox"/>	Inactive <input type="checkbox"/>	Not Started <input type="checkbox"/>	

1. Is this operation in compliance with the Safety Rules and Regulations? YES NO NOTED
2. Is this mine operating in compliance with the conditions of the mining permit? YES NO NOTED
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES NO NOTED

REMARKS AND RECOMMENDATIONS:

PLANT STILL NOT OPERATING -

FRONT END loader working in stock
pile area.

WATER IN PIT SWAMP CLEAR - (40') NOT
pumping.

I FOUND NO S + E CONTROL PROBLEMS.

Company Official Contacted Judy Sweigart
 Mine Inspector Jones Carpenter

Title Dispatcher
 Inspection Date 3-29-82

INSPECTORS' RECOMMENDATIONS TO BUREAU: