

Commonwealth of Pennsylvania

DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF SURFACE MINE RECLAMATION  
INSPECTION  
REPORT

Mini mit No. 733-5  
Drainage Permit No. 7974SM1  
Mine Inspection No. 54  
Reinspection No. J-82

Company <u>GENERAL CRUSHED STONE</u>	Mine Location: County <u>BUCKS</u>	Township <u>E. ROCK HILL</u>
Mining Permit Acres Affected <u>95</u>	Drainage Permit Acres Affected	
Status of Operation: Active <input checked="" type="checkbox"/>	Inactive <input type="checkbox"/>	Not Started <input type="checkbox"/>

1. Is this operation in compliance with the Safety Rules and Regulations? YES  NO  NOTED
2. Is this mine operating in compliance with the conditions of the mining permit? YES  NO  NOTED
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES  NO  NOTED

REMARKS AND RECOMMENDATIONS:

PLANT STILL DOWN

WATER IN PIT SWAMP RISING - NOT PUMPING

I FOUND NO S+E PROBLEMS

Company Official Contacted <u>Judy Sweigart</u>	Title
Mine Inspector <u>Jonas Carpenter</u>	Inspection Date <u>9-28-82</u>

INSPECTORS' RECOMMENDATIONS TO BUREAU: