PHOTOGRAPHS

Upslope (western) portion of site looking through gate on 51st St.

Mulched middle portion of site with green compost filter sock towards the upslope.

Permit No.: PAD510225
Report No.: 06- 9/4/24

PHOTOGRAPHS

Downslope section of site with large fill dirt stockpile in distance.

Remaining sediment stain on Bartram's Garden trail with large fill dirt stockpile in distance.

PHOTOGRAPHS

Remaining sediment stain on Bartram's Garden trail. Very bright spots in photo are patches of sunlight getting through the overhead railroad bridge.

End of photo log.