



**COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF MINING PROGRAMS**

Version: 3.0.1

Mining Activities Inspection Report

Inspection Type	RTNC - Routine/Complete Inspection	Permit Number	7974SM1
DEP Office	EP DMO Pottsville Dstr Mng Off	NPDES Number	PA0594121
Permittee Name	HANSON AGGREGATES PA LLC	PF Name	HANSON AGGREGATES PA ROCK HILL QUARRY
Address 1	7660 IMPERIAL WAY	Permit Type	IMMO - Industrial Mineral Mining Operation
Address 2		Permit Kind	LARGE - Surface Large
City	ALLENTOWN	License Number	24143
State/ZIP Code	PA 18195-1016	Permit Status	ACTIV - Active
Arrival Date / Time	05/19/2020 08:04 AM	Municipality	East Rockhill Township
Depart Date / Time	05/19/2020 03:00 PM	County	Bucks
Inspection ID	3068923	GP12 Permit Number	
Contract Operator Name		Contract Operator License Number	

Inspector Details

Inspector Name:	(608058) - AMIEE BOLLINGER	Inspector Telephone Number:	6109160100	Inspector Email:	ambollinge@pa.gov
------------------------	----------------------------	------------------------------------	------------	-------------------------	-------------------

Expiration Dates

Mining License	12/31/2020	Contractor License	03/31/2021
Mining Permit	07/19/2023 PENDING	NPDES Permit	07/19/2023 PENDING

Inspection Result

NOVIO - No Violations Noted

Findings

Erosion & Sedimentation

Approved E&S Plan	<input checked="" type="checkbox"/> Inspected	
-------------------	---	--

Operations

Mining Operation	<input checked="" type="checkbox"/> Inspected	Permit Conditions	<input checked="" type="checkbox"/> Inspected
Signs and Markers	<input checked="" type="checkbox"/> Inspected	Unauthorized Mining	<input checked="" type="checkbox"/> Inspected

Reclamation

Permit Conditions	<input checked="" type="checkbox"/> Inspected	Reclamation Plan	<input checked="" type="checkbox"/> Inspected
-------------------	---	------------------	---

Mining Area/Bonding

Adequate Bonding	<input checked="" type="checkbox"/> Inspected	
------------------	---	--

Compliance

Pattern Of Violations	<input checked="" type="checkbox"/> Inspected	
-----------------------	---	--

This Report is official notification that a representative of the Department of Environmental Protection has conducted an investigation of your operation. Violations observed by the Department have been noted on this report form.

If the Department uncovers any violations based on laboratory reports or further consideration of the conditions described in this report, the District Office will notify you of such violations in writing.

If an order was issued by the Department, you will be provided with a written confirmation of that order. You should not wait until you receive this confirmation Order before taking appropriate action.

This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal actions for any violation noted herein.

General Comments

On site to observe removal of equipment. Two loads of equipment went out. The haul roads were wetted and trucks were escorted in and out of the site. Prior to exiting, the lead vehicle and truck wheels were washed. All protocols approved by the Department on March 5, 2020 were followed.