

Commonwealth of Pennsylvania

DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF SURFACE MINE RECLAMATION
INSPECTION
REPORT

we

Mine No. 733-5
Drainage Permit No. 4974SM1
Mine Inspection No. 54
Reinspection No. 4-82

Company <u>GENERAL CRUSHED STONE</u>	Mine Location: County <u>BUCKS</u>	Township <u>E. ROCKHILL</u>
Mining Permit Acres Affected <u>95</u>	Drainage Permit Acres Affected	
Status of Operation: <input checked="" type="checkbox"/> Active	<input type="checkbox"/> Inactive	<input type="checkbox"/> Not Started

1. Is this operation in compliance with the Safety Rules and Regulations? YES NO NOTED
2. Is this mine operating in compliance with the conditions of the mining permit? YES NO NOTED
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES NO NOTED

REMARKS AND RECOMMENDATIONS:

*Loader handling from stock + stepping
in spare time.*

I found no S+E problems

*not pumping - 30' water over bottom
level*

Area to be flagged

Company Official Contacted *Judy Sweigart*
 Mine Inspector *Jonas Carpenter*

Title *General Mgr.*
 Inspection Date *8-2-82*

INSPECTORS' RECOMMENDATIONS TO BUREAU:

Commonwealth of Pennsylvania

DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF SURFACE MINE RECLAMATION
INSPECTION
REPORT

W

Min Permit No. 733-5(A2)
Drainage Permit No. 7974SM1
Mine Inspection No. J4
Reinspection No. 1-82

Company <u>GENERAL CRUSHED STONE</u>		Mine Location: County <u>Bucks</u>	Township <u>E. Rockhill</u>
Mining Permit Acres Affected <u>5.2</u>		Drainage Permit Acres Affected	
Status of Operation: Active	Inactive <input checked="" type="checkbox"/>	Not Started	

1. Is this operation in compliance with the Safety Rules and Regulations? YES ___ NO ___ NOTED ___
2. Is this mine operating in compliance with the conditions of the mining permit? YES ___ NO ___ NOTED ___
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES ___ NO ___ NOTED ___

REMARKS AND RECOMMENDATIONS:

Nothing being affected on this AREA AT Present

AREA TO be flagged

Company Official Contacted <i>Judy Swigart</i>	Title <i>General Mgr.</i>
Mine Inspector <i>Jonas Carpenter</i>	Inspection Date <i>8-2-82</i>

INSPECTORS' RECOMMENDATIONS TO BUREAU: