

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL PROTECTION  
BUREAU OF MINING AND RECLAMATION

**INSPECTION REPORT**

**NONCOAL**

Page 1 of 1  
Date 8/7/00  
On Site Times PM

Mine Name Rockhill Quarry  
Weather Sunny 85 F

PERMITTEE Hanson Aggregates of PA., INC.	TOWNSHIP East Rockhill	COUNTY Bucks	PERMIT NO. 7974SM1'
ADDRESS 1900 Sullivan Trail Easton, Pa. 18040 610-253-4271	VIOLETION HISTORY QNOV'S QCO'S	VIOLETIONS NOTED <input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> PREVIOUS VIOLATIONS: COMPLIANCE ORDER <input type="checkbox"/> CORRECTED <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> UNCORRECTED <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>	LICENSE NO. & EXP. DATE 3-00679 4/30/00 OPERATIONAL STATUS Active

**GENERAL MINING INFORMATION:** Large Noncoal  Small Noncoal  Complete  Partial or Followup

- a. Areas-Minerals-Pit Dimensions (L/W/H) – Method: Diabase Open Pit
- b. Acreage (total): 103.2(41.77ha) Bonded 103.2 Affected ~103 Regraded 0 Reclaimed 0
- c. Equipment-Use & Conditions: Processing Plant
- d. Contract Miner  yes  no
- e. Blasting at Site  yes  no (Explain yes answer) No Recent Blasting

**PERFORMANCE STANDARDS NONCOAL**

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
X	700 Unauthorized Mining				NA	730 Concurrent Reclamation			
X	701 Signs and Markers				NA	731 Backfilling and Grading			
NA	702 Casing and Sealing Drilled Holes				NA	733 Covering Coal and Acid/Toxic Mat.			
NA	703 Topsoil-Rem/Sto/Hnng				NA	735 Revegetation			
NA	704 Effluent Standard				NA	742 Permanent Mining Cessation			
X	706 Diversions and Conveyance				NA	743 Haul Roads/Restoration			
X	707 Sediment Control Measures				X	745 Support Facilities			
NA	708 Treatment Facilities				X	749 General Safety			
NA	709 Sedimentation Ponds				X	753 Permit Conditions			
NA	710 Discharge Structures				NA	754 Temporary Mining Cessation			
NA	711 Acid and Toxic Forming Spoil				NA	755 Closing Underground Mine Openings			
NA	712 Impoundments				NA	756 Distance Limitations-Barriers			
NA	713 Dams, Ponds-Design/Const./Maint.				NA	757 Bench			
NA	715 Water Monitoring-Ground/Surface				NA	758 Permit Line Setback			
NA	717 Water Rights and Replacement				NA	759 Stability Analysis			
NA	718 Water Discharge-Underground Mine				NA	760 Post Mining Renovation			
X	723 Blasting Requirement				NA	761 Postmining Land Use			
X	727 Disposal of Solid Wastes				NA	762 Cleanup			
X	728 Air Resources Protection								

**COMMENTS AND RECOMMENDATIONS:** This inspection conducted solo.

1. Identification sign has been re-erected at the entrance to the site.
2. Site appears as it did during the last inspection. There is no evidence of recent mining activity.
3. Water level is very high but no discharge was observed.
4. Lock on the gate has been replaced and a key sent to the department.
5. No violations were observed.

Person Contacted	Title	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
None		Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature		Range of Samples Collected Not Determined
Mailed		Investigator Signature & I.D. No. <i>Darryl Watter 149238</i> 4532

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

**District File/Permittee/Inspector**