

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

Mine Name Rock Hill Quarry
Weather raining - cold
(610) 253-4271

INSPECTION REPORT
NONCOAL

Date 12/11/96

On Site Times PM

PERMITTEE <u>Milestone Materials, Inc.</u>	TOWNSHIP <u>East Rockhill</u>	COUNTY <u>Bucks</u>	PERMIT NO. <u>79745M1</u>
ADDRESS <u>P.O. Box 231 1900 Sullivan Trail Easton, PA. 18044</u>	VIOLATION HISTORY <u>0 NOV'S 0 CO'S</u>	VIOLETIONS NOTED PREVIOUS VIOLATIONS: CORRECTED <input type="checkbox"/> UNCORRECTED <input type="checkbox"/>	FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> COMPLIANCE ORDER <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>
GENERAL MINING INFORMATION: Large Noncoal <input checked="" type="checkbox"/> Small Noncoal <input type="checkbox"/> Complete <input checked="" type="checkbox"/> Partial or Followup <input type="checkbox"/>			LICENSE NO. & EXP. DATE <u>3-00679 9/30/97</u>
a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: <u>Diabase - open pit quarry ~1500ft x 900ft x ~250ft - 5 lifts</u>			OPERATIONAL STATUS <u>Active ??</u>

b. Acreage (total): Bonded (103.2) 103.2 Affected ~103.2 Regraded --- Reclaimed ---

c. Equipment-Use & Conditions: To be determined

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers) (To be determined)

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
✓	700 Unauthorized Mining					730 Concurrent Reclamation			
✓	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Sto/Hndng					735 Revegetation			
✓	704 Effluent Standard					742 Permanent Mining Cessation			
	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures					745 Support Facilities			
	708 Treatment Facilities				✓	749 General Safety			
	709 Sedimentation Ponds				✓	753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
✓	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
	723 Blasting Requirement					761 Postmining Land Use			
	727 Disposal of Solid Wastes					762 Cleanup			
	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: I.D. sign is posted. Site entrance has gate locked. No one is on site. Garage, scalehouse and other buildings are boarded closed. This site has not been worked since 1991-2 as determined from past inspection reports. Inspector will contact the Operator to verify that a minimum of 500 tons of material has been removed from site in order to retain an active status. Water monitoring reports are up-to-date. There is no violation history for the past 2 years.

Person Contacted <u>Copy to be mailed</u>	Title	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no ?
Signature	Investigator Signature & I.D. No.	Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no ?
	<u>John Embick</u>	Range of Samples Collected _____ to _____
		<u>4 5 0 5</u>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.