

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

OFFICIAL USE ONLY

INSPECTION REPORT

Date 12-14-88

215-253-4271

PERMITTEE <u>The General Crushed Stone Company</u>	TOWNSHIP <u>E. ROCK HILL</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>79745M1</u>
ADDRESS <u>P.O. Box 231 1609 SULLIVAN TRAIL EASTON, PA. 18042</u>	TYPE OF INSPECTION Partial <input checked="" type="checkbox"/> Followup <input type="checkbox"/> Complete <input type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. <u>300733</u> Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date <u>12-31-88</u> Operational Status <u>Active</u>

A1. GENERAL MINING INFORMATION

- a. Seams DIABASE
- b. Highwall/s height/s: actual 250' - 5 LEVELS
bonded 101,700
- c. Length & Width of cut/s 1500' x 975'
- d. Total Acres: Permitted 103.2(103.2) Affected 103.2 Regraded Reclaimed
- e. Phase/s being mined: NONE

Unauthorized Mining 0 Acres Unauthorized Mining Activities 0 Acres

2. Method of Mining: QUARRING

3. Equipment: Use & Condition

4. Contract Miner yes no Name: _____ Address: _____

5. Blasting at Site: yes no Blaster's Name _____ License No. _____
Contract Blaster yes no Contractors name _____

6. Auger Permit Safety Permit No. _____
 yes no Active Inactive not started completed

7. Refuse Disposal Approved
 yes no Active (describe) Inactive

8. Previous Enforcement:

- a. Orders & Agreements outstanding yes no Type _____
- b. Adjudications Outstanding yes no Type _____
- c. Violations on Last Inspection yes no (If yes, explain status in remarks)

Person contacted <u>Tony Demare</u>	Title <u>april mgr</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR-5.2 attached.
Signature <u>Copy Mailed</u>	Investigator <u>Janeen Carpenter</u>	Signature <u>451016</u> I.D. No.

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 12-14-88

Permit Number <u>79745M1</u>	Township <u>E. ROCKHILL</u>	County <u>BUCKS</u>
Name of Permittee <u>The General Crushed Stone Company</u>		

C. Comments & Recommendations

NO ONE ON SITE AT TIME OF INSPECTION -
WATER STILL RISING IN PIT - 120' IT WALL
REMAINS -

OPERATOR STATED THAT HE HAS REMOVED
OVER 500^{TONS} OF MATERIAL FROM STOCK THIS YEAR

I FOUND NO STE PROBLEM

1 D SIGN POSTED

Operator _____ Signature _____ Date _____ Inspector Jonas Carpenter Signature _____