5600-FM-MR0005.7 Rev. 2/96

507216

# COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF MINING AND RECLAMATION

Mine Name Rockhill Quarry Weather Clear 35 F

# INSPECTION REPORT NONCOAL

Page 1 of 1 Date <u>12/03/2005</u> On Site Times <u>PM</u>

PERMITTEE Hanson Aggregates of Pa., Inc.		TOWNSHIP East Rockhill				COUNTY Bucks	PERMIT NO. 7974SM1		
		Last Ro				DUCKS			
	RESS	VIOLATION VIOLATIONS N			NOTE	Ioted 🗍 Follow-up Insp. Required 🗍			XP. DATE
190	0 Sullivan Trail	HISTORY	PREVIOUS V	REVIOUS VIOLATIONS; COMPLIANCE ORDER			9/	30/2006	
Eas	iton, Pa. 18040	ONOV'S CORRECTED FTC ORDER CEASE ORDER			OPERATIONAL STATUS				
610	-253-4271	0CO'S	CO'S UNCORRECTED OUTSTANDING ENFORCEMENT			Active			
GEN	ERAL MINING INFORMATION:	Large N	onco	oal 🕅 🛛 Sr	nall N	Ioncoal 🗌 Complete 🛛 Par	tial or Fol	lowu	рП
						Open Pit ~ 1500' (457m) x 900' (			
							21411772	00 11	0111
	creage (total): <u>103.3 (41.77ha)</u> Bo								
	quipment-Use & Conditions: <u>No ec</u>	guipmant	on si	te		5 3 8 3			
d. C	ontract Miner 🗌 yes 🛛 no	e. I	Blasti	ng at Site	🖂 ye	s 🔲 NO (Explain yes answer) <u>NO rece</u>	<u>ent blasting</u>	1	
			PERFO	DRMANCE ST	ANDA	RDS NONCOAL			
Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
X	700 Unauthorized Mining				NA	730 Concurrent Reclamation			
X	701 Signs and Markers	Noted			NA	731 Backfilling and Grading			
NA	702 Casing and Sealing Drilled Holes				NA	733 Covering Coal and Acid/Toxic Mat.			
X	703 Topsoil-Rem/Sto/Hnlng				NA	735 Revegetation			
X	704 Effluent Standard				NA	742 Permanent Mining Cessation			
NA	706 Diversions and Conveyance				X	743 Haul Roads/Restoration			
X	707 Sediment Control Measures				X	745 Support Facilities			
NA	708 Treatment Facilities				X	749 General Safety			
X	709 Sedimentation Ponds				X	753 Permit Conditions	1		
X	710 Discharge Structures		-		NA	754 Temporary Mining Cessation	1		
NA	711 Acid and Toxic Forming Spoil				NA	755 Closing Underground Mine Openings			
NA	712 Impoundments				X	756 Distance Limitations-Barriers	I		
	713 Dams, Ponds-Design/Const./Maint.				X	757 Bench			
NA	715 Water Monitoring-Ground/Surface				X	758 Permit Line Setback			
	717 Water Rights and Replacement				NA	759 Stability Analysis			l
NA	718 Water Discharge-Underground Mine				NA	760 Post Mining Renovation			
X	723 Blasting Requirement				NA	761 Postmining Land Use			
X	727 Disposal of Solid Wastes				NA	762 Cleanup	l		· · · · · · · · · · · · · · · · · · ·
X	728 Air Resources Protection		1				1		

COMMENTS AND RECOMMENDATIONS: This complete inspection was conducted solo. Mr. David Hill (Hanson) called and said that the required 500 tons had been removed from the quarry. No other mining activity was observed.

Violation History : None for the past 2 years.

Person Contacted	Title	Discharge/Seeps 🗌 yes 🛛	no
		Samples Collected	
None		Range of Samples Collected	No discharge
Signature		Investigator Signature	Sampler I.D. No. 4519
Mailed		abol Amiles	Balling Employee #608058

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

District File / Permittee / Inspector

1503217

### COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF MINING AND RECLAMATION

Page 1 of 1 Date <u>12/03/2005</u> On Site Times <u>PM</u>

Mine Name Rockhill Quarry Weather Clear 35 F

#### SAFETY INSPECTION PERMITTEE TOWNSHIP COUNTY PERMIT NO. Hanson Aggregates of Pa., Inc. East Rockhill 7974SM1 Bucks ADDRESS LICENSE NO. & EXP. DATE D PARTIAL FOLLOWUP COMPLETE 1900 Sullivan Trail 1848 9/30/2006 Easton, Pa. 18040 MSHA ID NO. VIOLATIONS NOTED 610-253-4271 □ FOLLOW-UP INSP. REQUIRED (Check One) PREVIOUS VIOLATIONS: Bituminous Surface COMPLIANCE ORDER CEASE ORDER CORRECTED Anthracite Surface UNCORRECTED FTC ORDER OUTSTANDING ENFORCEMENT Industrial Mineral Surface Obs. STANDARD Viol. Comp. Date Obs. STANDARD Viol. Comp. Date GENERAL PROVISIONS ELECTRICITY 209.1 Information to Workmen 209.81 Enclosing of Terminals Supervision to Operations 209.2 Criteria of Apparatus and Conductors 209.82 Safety Inspections 209.3 **Operation Near Power Lines** 209.83 SAFETY CLOTHING Protective Gloves and Tools 209.84 Headgear 209.11 209.85 Rubber Mats Shoes 209.12 Trailing Cables 209.86 Eye Protection 209.13 Protection of Electric Cables 209.87 EQUIPMENT FIRE PROTECTION Moving Parts and Gears 209.21 209.91 Fire Extinguishers Repair of Equipment 209.22 Flammable Liquids 209.92 209.23 Smoking and Open Lights 209.93 Catwalks Machines at Rest 209.24 ACTIVE OR ABANDONED DEEP MINES Mobile Machinery 209.25 Notification of Official 209,101 **Operating Equipment** 209.26 Protection of Employees 209.102 EXCAVATING **Openings in Abandoned Mines** 209.103 Angle of Earth Cuts 209.31 TIPPLES AND LOADING RAMPS 209.32 209.111 Removal of Rocks Equipment Required Upkeep of Low Walls 209.33 Ladders 209.112 Pipelines and Wells 209.34 Hazards to Passage 209.113 Night Operations 209.35 209.114 Lighting OXYGEN AND GAS Housekeeping 209.115 209.71 Marking Containers FIRST AID Restricted Use 209.72 209.121 Equipment Required Storage of Containers 209.73 209.122 Personnel Required Personnel and Equipment 209.74 ALL PERMITTED FACILITIES

X 11(B) Noncoal SMCRA

Permit Condition:

4.2 SMCRA

Obs.	STANDARD Obs.		STANDARD		STANDARD	
	INSPECTION OF MINE SITE		PERSONAL PROTECTION		AUGER MINING	
	Haulroad and Berms		Hearing Protection		Gas Detectors	
	Imminent Dangers Communications MOBILE EQUIPMENT		Loose Clothing Chemicals INSPECTION OF SURFACE FACILITY		Independent Contractor ID ELECTRICAL	
	Tires		Conveyor Belts		Secure Against Unauthorized Entry	
	Windshield		Stockpile Safety		Danger Signs	
	Back-up Alarm		Start Up Alarm			
	Seat Belts		Refuse Piles (General Safety)			
	Brakes		Electrical Lockouts			
	Dust Control (Drill)		Ponds and/or Impoundments			
	Drag Cables and Sheaves					

COMMENTS AND RECOMMENDATIONS:

Lighting Torches

Testing for Leaks

Transportation of Tanks

209.75

209.76

209.77

Person Contacted	Title	Investigator Signature and I.D. No. 608058	
None		Amiee Bollinger	
Signature		The Operator's signature acknowledges that he has read the report, including the	
To be mailed		reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report	
District File Description of a March			

## District File/Permittee/Inspector/MSHA