

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

OFFICIAL USE ONLY

Non Coal

INSPECTION REPORT

Date 12-4-85  
825 1100

PERMITTEE The General Crushed Stone Co.	TOWNSHIP E. Rockhill	COUNTY Berks	PERMIT NO. 7974SM1
ADDRESS P.O. Box 231 Easton, Pa. 18042	TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input type="checkbox"/> Complete <input checked="" type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. <u>300733</u> Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date <u>12-31-85</u> Operational Status <u>ACTIVE</u>

A1. GENERAL MINING INFORMATION

- a. Seams Diabase
  - b. Highwall/s height/s: actual 250 ft. == 5 levels  
bonded 101,700
  - c. Length & Width of cut/s 1500 X 775 ft
  - d. Total Acres: Permitted 103.2(103.2) Affected All Regraded 0 Reclaimed 0
  - e. Phase/s being mined: None
- Unauthorized Mining 0 Acres  Unauthorized Mining Activities 0 Acres

2. Method of Mining: Quarring

3. Equipment: Use & Condition FRONT END LOADER  
Good.

4. Contract Miner  yes  no Name: \_\_\_\_\_ Address: \_\_\_\_\_

5. Blasting at Site:  yes  no Blaster's Name \_\_\_\_\_ License No. \_\_\_\_\_  
Contract Blaster  yes  no Contractors name \_\_\_\_\_

6. Auger Permit Safety Permit No. \_\_\_\_\_  
 yes  no  Active  Inactive  not started  completed

7. Refuse Disposal Approved  yes  no  Active (describe)  Inactive

8. Previous Enforcement:

- a. Orders & Agreements outstanding  yes  no Type \_\_\_\_\_
- b. Adjudications Outstanding  yes  no Type \_\_\_\_\_
- c. Violations on Last Inspection  yes  no (If yes, explain status in remarks)

Person contacted <u>Joseph Bronico</u> Signature <u>Joseph Bronico</u>	Title <u>Off. Mgr.</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____	ER-MR-5.2 attached.
		Investigator <u>Jonas Carpenter</u> Signature	<u>41506</u> I.D. No.

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 12-4-85

Permit Number <u>7974SM1</u>	Township <u>E. Rockhill</u>	County <u>Bucks</u>
---------------------------------	--------------------------------	------------------------

Name of Permittee  
The General Crushed Stone Co.

C. Comments & Recommendations

There has been no mining for PLANT AT THIS MINE SINCE 1980. EVERY YEAR MATERIAL IS LOADED FROM STOCK TO KEEP PERMIT ACTIVE - THERE IS SOME STRIPPING IN PROGRESS BUT NO MINING -

THE WATER IN PIT IS NOW 2 1/2 LEVELS DEEP - APP 125' AND STILL RISING - NO PUMPING OR BLASTING SINCE 1980.

ID SIGN POSTED.

I FOUND NO PROBLEMS WITH STE.

Operator Joel Brown Signature Date Inspector James Carpenter Signature