

Commonwealth of Pennsylvania

DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF SURFACE MINE RECLAMATION  
INSPECTION  
REPORT

Permit No. 733-5  
Drainage Permit No. 7974SM1  
Mine Inspection No. 54  
Reinspection No. 2

Company <u>General Crushed Stone Co</u>	Mine Location: County <u>Bucks</u>	Township <u>East Rockhill</u>
Mining Permit Acres Affected <u>15</u>	Drainage Permit Acres Affected <u>30</u>	
Status of Operation: Active <input checked="" type="checkbox"/>	Inactive <input type="checkbox"/>	Not Started <input type="checkbox"/>

1. Is this operation in compliance with the Safety Rules and Regulations? YES  NO  NOTED
2. Is this mine operating in compliance with the conditions of the mining permit? YES  NO  NOTED
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES  NO  NOTED

REMARKS AND RECOMMENDATIONS: water sample #PS 2160 taken from same location as water sample #PS 2137. water cloudy.

A horizontal bench at least 25 feet in width shall be maintained between successive faces where multiple benching is required.

No combustible material permitted within 25 feet of the magazines - explosives storage.

Erosion must be controlled - desilting facilities should be monitored on a regular basis. (As noted - water sample #PS 2160 was cloudy).

Broken window on power shovel cab is to be replaced promptly.

T 366 is a private road on General Crushed Stone

Company Official Contacted <u>Joe Cival &amp; James Fryer</u>	Title <u>Supervisors</u>
Mine Inspector <u>Paul T. Serfers</u>	Inspection Date <u>12-9-77</u>

INSPECTORS' RECOMMENDATIONS TO BUREAU: water sample #PS 2160 has been submitted to the Harrisburg laboratory for analysis. If the sample does not meet water quality standards - this operator is to be charged with the violation.

Note: Sample #PS 2137 suspended solids were recorded at 46.