

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

OFFICIAL USE ONLY

INSPECTION REPORT

Date 2-1-88

PERMITTEE <u>The General Crushed Stone Company</u>	TOWNSHIP <u>EAST ROCKWILL</u>	COUNTY <u>BLUES</u>	PERMIT NO. <u>7974SM1</u>
ADDRESS <u>P.O. Box 231 EASTON PENNSYLVANIA 18042 215-253-4271</u>	TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input type="checkbox"/> Complete <input checked="" type="checkbox"/>	STATUS Violation/s Noted <input checked="" type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. <u>300733</u> Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date <u>12-31-88</u> Operational Status <u>ACTIVE</u>

A1. GENERAL MINING INFORMATION

- a. Seams DIABASE
- b. Highwall/s height/s: actual 250' - 9 levels  
bonded 101,700
- c. Length & Width of cut/s 1500' x 775'
- d. Total Acres: Permitted 103.2 (103.2) Affected 103.2 Regraded 0 Reclaimed 0
- e. Phase/s being mined: NONE

Unauthorized Mining 0 Acres  Unauthorized Mining Activities 0 Acres

2. Method of Mining: QUARRING

3. Equipment: Use & Condition F.E.L.  
OLD

4. Contract Miner  yes  no Name: \_\_\_\_\_ Address: \_\_\_\_\_

5. Blasting at Site:  yes  no Blaster's Name \_\_\_\_\_ License No. \_\_\_\_\_  
Contract Blaster  yes  no Contractors name \_\_\_\_\_

6. Auger Permit Safety Permit No. \_\_\_\_\_  
 yes  no  Active  Inactive  not started  completed

7. Refuse Disposal Approved  yes  no  Active (describe)  Inactive

8. Previous Enforcement:

- a. Orders & Agreements outstanding  yes  no Type \_\_\_\_\_
- b. Adjudications Outstanding  yes  no Type \_\_\_\_\_
- c. Violations on Last Inspection  yes  no (If yes, explain status in remarks)

Person contacted <u>GARY V. TAYLOR</u>	Title <u>F.C.M.</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR-5.2 attached.
Signature <u>[Signature]</u>	Investigator <u>James Carpenter</u>	Signature <u>[Signature]</u> I.D. No. <u>415016</u>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

N.O.V.

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

## INSPECTION REPORT

Date 2-1-88

Permit Number

7974 SM1

Township

EAST ROCKHILL

County

BUCKS

Name of Permittee

The GENERAL CRUSHED STONE COMPANY

## C. Comments &amp; Recommendations

VIOLATION - S + E BERM REMOVED BY OTHERS TO PERMIT A.T.V. TO ENTER PERMIT AREA WHICH IS CAUSING EMINENT DANGER - NOTED THIS IS CAUSED BY OTHERS BUT MORE CARE MUST BE TAKEN TO KEEP THEM OUT -

TO REMOVE VIOLATION OPERATOR TO CORRECT BERM BREAK + PLACE LARGE STONE ON OUTSIDE OF ENTRANCE TO KEEP A.T.V. OUT -

BETTER BLOCKAGE TO BE INSTALLED AT ENTRANCE'S ROADS -

OPERATOR GIVEN UNTILL 2-11-88 TO CORRECT PROBLEM

I.D. SIGN IN PLACE -

Operator

Signature

[Signature]

Date

Date

Inspector

Signature

[Signature]