

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF MINING AND RECLAMATION

Mine Name Rockhill Quarry
Weather N/A

INSPECTION REPORT
NONCOAL

Date 2/2/99

On Site Times N/A

PERMITTEE <u>Milstone Materials Inc.</u>	TOWNSHIP <u>E. Rockhill</u>	COUNTY <u>Bucks</u>	PERMIT NO. <u>7974SM1</u>
ADDRESS <u>P.O. Box 231 Easton, PA 18044 610-253-4271</u>	VIOLATION HISTORY <u>0</u> NOV'S <u>0</u> CO'S <u>any</u>	VIOLETIONS NOTED <input checked="" type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input checked="" type="checkbox"/> PREVIOUS VIOLATIONS: COMPLIANCE ORDER <input type="checkbox"/> CORRECTED <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> UNCORRECTED <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>	LICENSE NO. & EXP. DATE <u>3-00679 4/30/99</u> OPERATIONAL STATUS <u>Active</u>

GENERAL MINING INFORMATION: Large Noncoal 1 Small Noncoal _____ Complete _____ Partial or Followup

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method:

b. Acreage (total): Bonded N/A Affected _____ Regraded _____ Reclaimed _____

c. Equipment-Use & Conditions:

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers)

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
	700 Unauthorized Mining					730 Concurrent Reclamation			
	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat.			
	703 Topsoil-Rem/Sto/Hndlng					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures					745 Support Facilities			
	708 Treatment Facilities					749 General Safety			
	709 Sedimentation Ponds					753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const./Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
	723 Blasting Requirement					761 Postmining Land Use			
	727 Disposal of Solid Wastes					762 Cleanup			
	728 Air Resources Protection								
						<u>1 SMPRA-1984-219</u>		<u>Sept 18 (V)</u>	<input checked="" type="checkbox"/>

COMMENTS AND RECOMMENDATIONS: Milstone materials Inc. is in violation of Section 12, Part (U) Progress Report of SMPRA-1984-219. The 1998 Noncoal mineral production Surface Mining Operations Annual Report should be submitted to the Department immediately.

Person Contacted <u>None</u>	Title	Discharge/Seeps <input type="checkbox"/> yes <input type="checkbox"/> no Samples Collected <input type="checkbox"/> yes <input type="checkbox"/> no <u>N/A</u> Range of Samples Collected _____ to _____
Signature <u>To be mailed</u>	Investigator Signature & I.D. No. <u>Christian Huber</u> 4 5 5 6	

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not