



2247995

Date 2/20/2014

Mine Name Rock Hill Quarry

**INSPECTION REPORT
NONCOAL**

On Site Times 1140

Weather Clear 40° F

Complete Partial

PERMITTEE Hanson Aggregates Pennsylvania, LLC	TOWNSHIP East Rockhill	COUNTY Bucks	PERMIT NO. 7974SM1
ADDRESS 7660 Imperial Way Allentown PA 18195 610-366-4828	VIOLATION HISTORY 0 NOV'S 0 CO'S	<input type="checkbox"/> VIOLATIONS NOTED PREVIOUS VIOLATIONS: <input type="checkbox"/> CORRECTED <input type="checkbox"/> UNCORRECTED	<input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> COMPLIANCE ORDER <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER
LICENSE NO. & EXP. DATE 24143 12/31/2014			OPERATIONAL STATUS Active

GENERAL MINING INFORMATION: Large Small 10,000 2,000 GP 105 GP 103 Expiration Date

- a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: Argillite
open pit- water filled pit- ~1500' x ~900' x ~250'
- b. Equipment-Use & Conditions: FEL- good condition
- c. Contract Miner: Yes No Name _____
- d. Approved Blast Plan: Yes No Is there blasting today? Yes No

Approved Acres	Approved Pit Volume	Progress of Reclamation		Liability
Mining Area: 103.2 Support:	yd ³	Regraded _____ acres	Topsoiled _____ acres	Current Bond
Disturbed not planted:	Current Pit Volume	Water Impoundment : Acres Approved _____ Acres Actual _____		\$203,400
Affected acres	yd ³	Planted, Grasses _____ acres		Current Liability
Mining Area: 103.2 Support:	Selective Grading of Highwall	Trees Required _____ ac. Planted _____ ac.		\$
Disturbed not planted:	Approved: yd ³ Current:	Meeting Stage 1 criteria: _____ acres		
Highwall Bond (Blasting to achieve reclamation) Approved/Affected				
<20 ft.:	ft.	ft.	>20<30 ft.	ft.
			ft.	ft.
			>30<40 ft.	ft.
			ft.	ft.
			>40<50 ft.	ft.
			ft.	ft.
			>50 ft.	ft.
			ft.	ft.

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	Unauthorized Mining		<input type="checkbox"/>		<input type="checkbox"/>	Air Resources Protection		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Mining License		<input type="checkbox"/>		<input type="checkbox"/>	Concurrent Reclamation		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Signs and Markers		<input type="checkbox"/>		<input type="checkbox"/>	Backfilling and Grading		<input type="checkbox"/>	
<input type="checkbox"/>	Topsoil-Rem/Storage/Handling		<input type="checkbox"/>		<input type="checkbox"/>	Revegetation		<input type="checkbox"/>	
<input type="checkbox"/>	Effluent Standard		<input type="checkbox"/>		<input type="checkbox"/>	Haul Roads		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Diversions and Conveyance		<input type="checkbox"/>		<input checked="" type="checkbox"/>	General Safety		<input type="checkbox"/>	
<input type="checkbox"/>	Sediment Control Measures		<input type="checkbox"/>		<input checked="" type="checkbox"/>	Permit Conditions		<input type="checkbox"/>	
<input type="checkbox"/>	Treatment Facilities		<input type="checkbox"/>		<input type="checkbox"/>	Temporary Mining Cessation		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Sedimentation Ponds		<input type="checkbox"/>		<input type="checkbox"/>	Distance Limitations-Barriers		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Discharge Structures		<input type="checkbox"/>		<input type="checkbox"/>	Bench Development		<input type="checkbox"/>	
<input type="checkbox"/>	Dams, Ponds-Design/Const./Maint.		<input type="checkbox"/>		<input type="checkbox"/>	Permit Line Setback		<input type="checkbox"/>	
<input checked="" type="checkbox"/>	Water Monitoring-Ground/Surface		<input type="checkbox"/>		<input type="checkbox"/>	Stability Analysis		<input type="checkbox"/>	
<input type="checkbox"/>	Water Discharge-Underground Mine		<input type="checkbox"/>		<input type="checkbox"/>			<input type="checkbox"/>	
<input type="checkbox"/>	Blasting Requirement		<input type="checkbox"/>		<input type="checkbox"/>			<input type="checkbox"/>	

COMMENTS AND RECOMMENDATIONS: This complete inspection was conducted solo. The front gate was unlocked. No activity was observed. Site inaccessible due to snow.

Violation History: None for the past two years.

Person Contacted None	Title	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no	Samples Collected <input type="checkbox"/> yes <input type="checkbox"/> no	Range of Samples Collected	to
Signature mailed		Investigator Signature Amiee Bollinger	Collector ID No. 4519	Employee ID No. 608058	

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

White - District File

Yellow - Permittee

Pink - Inspector