

OFFICIAL USE ONLY

### INSPECTION REPORT

Date 2-25-87

PERMITTEE <u>The General Crushed Stone Company</u>	TOWNSHIP <u>EAST ROCKHILL</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>7974541</u>
ADDRESS <u>P.O. Box 231 EASTON, PA 18042</u>	TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input type="checkbox"/> Complete <input checked="" type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. <u>300-783</u> Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date <u>12-31-87</u> Operational Status <u>ACTIVE</u>

#### A1. GENERAL MINING INFORMATION

- a. Seams DIMBASE
- b. Highwall/s height/s: actual 250'-5 LEVELS  
bonded 101,700
- c. Length & Width of cut/s 1500' x 775'
- d. Total Acres: Permitted 103.2 (103.2) Affected 103.2 Regraded 0 Reclaimed 0
- e. Phase/s being mined: NOISE 7.33-5

Unauthorized Mining 0 Acres     Unauthorized Mining Activities 0 Acres

2. Method of Mining: QUARRING

3. Equipment: Use & Condition FEL

4. Contract Miner    Name: \_\_\_\_\_  
 yes     no    Address: \_\_\_\_\_

5. Blasting at Site:     yes     no    Blaster's Name \_\_\_\_\_ License No. \_\_\_\_\_  
Contract Blaster  yes     no    Contractors name \_\_\_\_\_

6. Auger Permit    Safety Permit No. \_\_\_\_\_  
 yes     no     Active     Inactive     not started     completed

7. Refuse Disposal Approved  
 yes     no     Active (describe)     Inactive

#### 8. Previous Enforcement:

- a. Orders & Agreements outstanding     yes     no    Type \_\_\_\_\_
- b. Adjudications Outstanding     yes     no    Type \_\_\_\_\_
- c. Violations on Last Inspection     yes     no    (If yes, explain status in remarks)

Person contacted <u>GARY V TAYLOR</u>	Title <u>FIELD CONST. MANAGER</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____
Signature <u>Gary V Taylor</u>	Investigator <u>Jonas Compton</u>	ER-MR-5.2 attached. <input type="checkbox"/> Signature <u>[Signature]</u> I.D. No. <u>45106</u>

Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 2-25-87

Permit Number 7974SM1 Township EAST ROCKHILL County BUCKS

Name of Permittee The General Crushed Stone Company

C. Comments & Recommendations

This plant has not operated for  
years.

Water level in pit app 130' -

I found no S + E problems -

The total area covered by snow.

ID sign posted.

Operator [Signature]  
Signature

2/25/87  
Date

Inspector [Signature]  
Signature