

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF MINING AND RECLAMATION

Mine Name ROCKHILL QUARRY
Weather SUNNY 30°

INSPECTION REPORT
NONCOAL

Date 1/22/01
On Site Times PM

PERMITTEE <u>HANSON AGGREGATES OF PA. INC.</u>	TOWNSHIP <u>EAST ROCKHILL</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>79745M1</u>
ADDRESS <u>1900 SULLIVAN TRAIL EASTON PA. 18040</u> <u>610-253-4271</u>	VIOLATION HISTORY <u>0</u> NOV'S <u>0</u> CO'S	VIOLETIONS NOTED <input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> PREVIOUS VIOLATIONS: COMPLIANCE ORDER <input type="checkbox"/> CORRECTED <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> UNCORRECTED <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>	LICENSE NO. & EXP. DATE <u>3-00679 9/30/01</u> OPERATIONAL STATUS <u>ACTIVE</u>

GENERAL MINING INFORMATION: Large Noncoal Small Noncoal Complete Partial or Followup

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: DIABASE - OPEN PIT

b. Acreage (total): 103.2 (41.77ha) Bonded 103.2 Affected ~103.2 Regraded Reclaimed

c. Equipment-Use & Conditions: PROCESSING PLANT

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers) NO RECENT BLASTING

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining				NA	730 Concurrent Reclamation			
<input checked="" type="checkbox"/>	701 Signs and Markers					731 Backfilling and Grading			
NA	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat.			
NA	703 Topsoil-Rem/Sto/Hnding					735 Revegetation			
<input checked="" type="checkbox"/>	704 Effluent Standard					742 Permanent Mining Cessation			
<input checked="" type="checkbox"/>	706 Diversions and Conveyance					743 Haul Roads/Restoration			
<input checked="" type="checkbox"/>	707 Sediment Control Measures					745 Support Facilities			
NA	708 Treatment Facilities					749 General Safety			
<input checked="" type="checkbox"/>	709 Sedimentation Ponds					753 Permit Conditions			
<input checked="" type="checkbox"/>	710 Discharge Structures				NA	754 Temporary Mining Cessation			
NA	711 Acid and Toxic Forming Spoil				NA	755 Closing Underground Mine Openings			
<input checked="" type="checkbox"/>	712 Impoundments					756 Distance Limitations-Barriers			
NA	713 Dams, Ponds-Design/Const./Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement				NA	759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement					761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes					762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: THIS INSPECTION CONDUCTED 'SOLO'
 (1) ID SIGN HAS NOT YET BEEN RE-BRKTED
 (2) NO ACTIVITY ON THIS DATE - GATE LOCKED
 (3) B+S CONTROLS ADEQUATE - NO DISCHARGE
 (4) NO BLASTING SINCE LAST INSPECTION
 (5) NO VIOLATIONS OBSERVED

Person Contacted <u>NONE</u>	Title	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature <u>MARCO 1/22/01</u>	Investigator Signature & I.D. No. <u>D. Walter 149238</u>	Range of Samples Collected _____ to _____