

2083010

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL PROTECTION  
BUREAU OF MINING AND RECLAMATION

**INSPECTION REPORT  
NONCOAL**

Page 1 of 1  
Date 7/12/2012  
On Site Times AM

Mine Name Rock Hill Quarry  
Weather Clear 75 F

PERMITTEE Hanson Aggregates of Pa., Inc.	TOWNSHIP East Rockhill	COUNTY Bucks	PERMIT NO. 7974SM1
ADDRESS 7660 Imperial Way Allentown PA 18195 610-366-4828	VIOLATION HISTORY QNOV'S QCO'S	VIOLATIONS NOTED <input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> PREVIOUS VIOLATIONS: COMPLIANCE ORDER <input type="checkbox"/> CORRECTED <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> UNCORRECTED <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>	LICENSE NO. & EXP. DATE 24143 12/31/2012 OPERATIONAL STATUS Active


- GENERAL MINING INFORMATION:** Large Noncoal  Small Noncoal  Complete  Partial or Followup
- a. Areas-Minerals-Pit Dimensions (L/W/H) – Method: Diabase Open Pit ~ 1500' (457m) x 900' (274m) x 250' (76m)
- b. Acreage (total): 103.3 (41.77ha) Bonded 103.2 Affected ~103 Regraded 0 Reclaimed 0
- c. Equipment-Use & Conditions: No equipment on site
- d. Contract Miner  yes  no e. Blasting at Site  yes  no (Explain yes answer) No recent blasting

**PERFORMANCE STANDARDS NONCOAL**

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
X	700 Unauthorized Mining				NA	730 Concurrent Reclamation			
X	701 Signs and Markers				NA	731 Backfilling and Grading			
NA	702 Casing and Sealing Drilled Holes				NA	733 Covering Coal and Acid/Toxic Mat.			
X	703 Topsoil-Rem/Sto/Hning				NA	735 Revegetation			
X	704 Effluent Standard				NA	742 Permanent Mining Cessation			
NA	706 Diversions and Conveyance				X	743 Haul Roads/Restoration			
X	707 Sediment Control Measures				X	745 Support Facilities			
NA	708 Treatment Facilities				X	749 General Safety			
X	709 Sedimentation Ponds				X	753 Permit Conditions			
X	710 Discharge Structures				NA	754 Temporary Mining Cessation			
NA	711 Acid and Toxic Forming Spoil				NA	755 Closing Underground Mine Openings			
NA	712 Impoundments				X	756 Distance Limitations-Barriers			
NA	713 Dams, Ponds-Design/Const./Maint.				X	757 Bench			
NA	715 Water Monitoring-Ground/Surface				X	758 Permit Line Setback			
NA	717 Water Rights and Replacement				NA	759 Stability Analysis			
NA	718 Water Discharge-Underground Mine				NA	760 Post Mining Renovation			
X	723 Blasting Requirement				NA	761 Postmining Land Use			
X	727 Disposal of Solid Wastes				NA	762 Cleanup			
X	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: This complete inspection was conducted solo. The gate was locked. No activity was observed.

Violation History: None

Person Contacted None	Title	Discharge/Seeps <input type="checkbox"/> yes <input type="checkbox"/> no Samples Collected <input type="checkbox"/> yes <input type="checkbox"/> no Range of Samples Collected
Signature	Investigator Signature	Sampler I.D. No. 4519
Mailed	Amiee Bollinger 	Employee #608058

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

**District File / Permittee / Inspector**