

Commonwealth of Penn.

DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF SURFACE MINE RECLAMATION
INSPECTION
REPORT

Mini Pit No. 733-5
Drainage Permit No. 7974 SMI
Mine Inspection No. 54
Reinspection No. 1-78

Company <u>General Crushed Stone Co</u>	Mine Location: County <u>Bucks</u>	Township <u>East Pothill</u>
Mining Permit Acres Affected <u>15</u>	Drainage Permit Acres Affected <u>30</u>	
Status of Operation: Active <input checked="" type="checkbox"/>	Inactive <input type="checkbox"/>	Not Started <input type="checkbox"/>

1. Is this operation in compliance with the Safety Rules and Regulations? YES NO NOTED
2. Is this mine operating in compliance with the conditions of the mining permit? YES NO NOTED
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES NO NOTED

REMARKS AND RECOMMENDATIONS: Water clear at discharge point, located near RR switch.
Industrial Waste Permit #0971205 covers this operation.
 (1) Several acres of the storage yard is located outside of the permitted area.
 (2) The sediment control pond - located adjacent to Pond #6, is filled with silt.
 (3) Map #5 of 6 shows 50 foot benches.
 (4) Operator to check location of waste dump - must be located on permitted area.
Conditions noted under (1), (2), (3) & (4) to be corrected within 30 days.

Company Official Contacted <u>James Fryer</u>	Title <u>Supervisor</u>
Mine Inspector <u>Paul J. Surfass</u>	Inspection Date <u>7-18-78</u>

INSPECTORS' RECOMMENDATIONS TO BUREAU: Is Industrial Waste Permit 0971205 a part of this MDP and enforced by the Bureau of Surface Mine Reclamation? If so - should the Dist #54 Inspector have a copy?

The Operator has 30 days to correct the above noted site problems.
No Central Office action necessary at this time.