5600-FM-BMP0491 10/2014
pennsylvania
bepartment of environmental protection

COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF MINING PROGRAMS

Page 1 of <u>1</u>

Date <u>6/16/2017</u>

On Site Times <u>0924 - 0950</u>

Pink - Inspector

Mine Name <u>Rock Hill Quarry</u> Weather <u>Rain</u> 63 F

☐ White - District File

NPDES INSPECTION REPORT

PERMITTEE Hanson Aggregates Pennsylvania,		TOWNSHIP East Rockhill	1			COUNTY Bucks		MINING PERMIT NO. 7974SM1		
ADDRESS 7660 Imperial Way Allentown PA 18195		PREVIOUS VIO	L VIOLATIONS NOTED			☐ FOLLOW-UP INSP. REQUIRED ☐ NOTICE OF VIOLATION ☐ COMPLIANCE ORDER ☐ FTC ORDER: ☐ CEASE ORDER		NPDES PERMIT NO. PA0594121 EXPIRATION DATE 7/19/2018		
SITE REVIEW										
OUTFALL TYPE DISCHARGING? SAMPLED? OUTFALL TYPE DISCHARGING? Sediment Treatment Yes No NIA OUTFALL TYPE DISCHARGING? Sediment Treatment Yes No NIA OUTFALL TYPE DISCHARGING? Sediment Treatment Yes No Yes										
Are any of the outfalls indicated as having no discharge? ☒ Yes ☐ No Were the DMRs signed? ☒ Yes ☐ No										
NPDES COMPLIANCE CHECKLIST										
[Obs.]	STANDARD	PC or REg.	NPD Viol.	Comp. Date	Obs.	STANDARD	PC or REg.	Viol.	Comp. Date	
Obs.	Treatment pond 2-year Effluent Characterization sampling Requirement	40 CFR 122.21(k)(5)(vi)			⊠	NPDES Permit Requirements	92a.41(a)1			
	Stormwater 2-year Effluent Characterization sampling Requirement	40 CFR 122.26(c)(1)(i)(G)				Failure to Report NPDES Non-Compliance	92a.41			
⊠	Reporting Requirements	40 CFR 122.41(I)				Failure to Submit DMR Data	92a.61(g)			
×	PPC Plan	Standard Cond 4			Ø	Implementation of E & S Plan Requirements	NPDES Permit Condition 1			
COMMENTS AND RECOMMENDATIONS: Water was not discharging.										
Person Contacted Title None Investigator Signature				☐ Cor	Inspection Done: Complete Partial Date: 6/16/2017 Employee ID No. 608058			o. 608058		
Amiee Bollinger										

☐ Yellow - Permittee