

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

Mine Name ROCK HILL  
Weather SUNNY

INSPECTION REPORT  
NONCOAL

Date 6-26-90  
On Site Times AM -

PERMITTEE <u>The General Crushed Stone Co</u>	TOWNSHIP <u>E. ROCK HILL</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>79745NAJ</u>
ADDRESS <u>P.O. BOX 231 1609 SULLIVAN TRAIL - EASTON PA 18042</u>	VIOLETION HISTORY ____NOV'S ____CO'S	VIOLETIONS NOTED PREVIOUS VIOLATIONS: CORRECTED <input type="checkbox"/> UNCORRECTED <input type="checkbox"/>	FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> COMPLIANCE ORDER <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>
GENERAL MINING INFORMATION: Large Noncoal <input checked="" type="checkbox"/> Small Noncoal _____ Complete <input checked="" type="checkbox"/> Partial or Followup _____		LICENSE NO. & EXP. DATE <u>300 733-12-31-90</u>	
a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: <u>1500' X 915' X 250' - 5 LIFTS</u> <u>OPEN PIT - DIABASE QUARRY</u>		OPERATIONAL STATUS <u>ACTIVE</u>	

b. Acreage (total): Bonded 103.7 Affected 103.7 Regraded 0 Reclaimed 0

c. Equipment-Use & Conditions:  
NONE

d. Contract Miner  yes  no e. Blasting at Site  yes  no (Explain yes answers)

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
<input checked="" type="checkbox"/>	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Sto/Hndng					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
	706 Diversions and Conveyance.					743 Haul Roads/Restoration			
	707 Sediment Control Measures					745 Support Facilities			
	708 Treatment Facilities				<input checked="" type="checkbox"/>	749 General Safety			
	709 Sedimentation Ponds				<input checked="" type="checkbox"/>	753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement				<input checked="" type="checkbox"/>	761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes					762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: WATER IN PIT HAS ROSE app 10'

Person Contacted <u>VERN SNYDER</u>	Title <u>Geo</u>	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature <u>Vern Snyder</u>	Investigator Signature & I.D. No. <u>Jonas Carpenter</u>	Range of Samples Collected _____ to _____
		<u>4 5 0 6</u>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.