

Commonwealth of Penns. 3

DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF SURFACE MINE RECLAMATION
INSPECTION
REPORT

Mini. nit No. 733-5 etc
Drainage Permit No. 7974SM 1
Mine Inspection No. 54
Reinspection No. 3-81

Company <u>General Crushed Stone Co</u>	Mine Location: County <u>Bucks</u>	Township <u>E. ROCKHILL</u>
Mining Permit Acres Affected <u>70</u>	Drainage Permit Acres Affected <u>70</u>	
Status of Operation: Active <input checked="" type="checkbox"/>	Inactive <input type="checkbox"/>	Not Started <input type="checkbox"/>

1. Is this operation in compliance with the Safety Rules and Regulations? YES NO NOTED
2. Is this mine operating in compliance with the conditions of the mining permit? YES NO NOTED
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES NO NOTED

REMARKS AND RECOMMENDATIONS:

FRONT END loader loading from stock - Crusher NOT yet operating

WATER IN PIT Sump clear - not pumping - very little change in depth.

I Found no problems with STE CONTROLS

There has been some STREPPING since last inspection

Company Official Contacted

Mine Inspector

Judy Sweigart
Jonas Carpenter

Title

Inspection Date

Dispatcher
6-7-82

INSPECTORS' RECOMMENDATIONS TO BUREAU: