

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION  
Non Coal

OFFICIAL USE ONLY

INSPECTION REPORT

Date 6-7-85

PERMITTEE The General Crushed Stone Co.	TOWNSHIP E. Rockhill	COUNTY Bucks	PERMIT NO. 7974SM1
ADDRESS P.O. Box 231 Easton, Pa. 18042	TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input type="checkbox"/> Complete <input checked="" type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. <u>300733</u> Valid Yes <input type="checkbox"/> No <input type="checkbox"/> Expiration Date _____ Operational Status <u>ACTIVE</u>

A1. GENERAL MINING INFORMATION

- a. Seams Diabase
  - b. Highwall/s height/s: actual 250 ft = 5 lifts  
bonded \_\_\_\_\_
  - c. Length & Width of cut/s 1500 X 775 ft
  - d. Total Acres: Permitted 103.2 (109.2) Affected All Regraded 0 Reclaimed 0
  - e. Phase/s being mined: None
- Unauthorized Mining 0 Acres  Unauthorized Mining Activities 0 Acres

2. Method of Mining: Quarrying

3. Equipment: Use & Condition Satisfactory

4. Contract Miner  yes  no Name: \_\_\_\_\_ Address: \_\_\_\_\_

5. Blasting at Site:  yes  no Blaster's Name \_\_\_\_\_ License No. \_\_\_\_\_  
Contract Blaster  yes  no Contractors name \_\_\_\_\_

6. Auger Permit Safety Permit No. \_\_\_\_\_  
 yes  no  Active  Inactive  not started  completed

7. Refuse Disposal Approved  
 yes  no  Active (describe)  Inactive

8. Previous Enforcement:

- a. Orders & Agreements outstanding  yes  no Type \_\_\_\_\_
- b. Adjudications Outstanding  yes  no Type \_\_\_\_\_
- c. Violations on Last Inspection  yes  no (If yes, explain status in remarks)

Person contacted <u>GARRY TAYLOR</u> Signature	Title <u>Cons Mgr</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____	ER-MR-5.2 attached.
The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.		Investigator <u>James Carpenter</u> Signature	<u>EA216</u> I.D. No.

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 6-7-85

Permit Number <u>7974SM1</u>	Township <u>E. Rockhill</u>	County <u>Bucks</u>
---------------------------------	--------------------------------	------------------------

Name of Permittee  
The General Crushed Stone Co.

C. Comments & Recommendations

*WATER IN PIT 85' deep.*

*Removed 5000' TON from stock pile*

Operator *[Signature]* 6/7/85 Inspector *[Signature]*  
Signature Date Signature