

Commonwealth of Pennsylvania

Mini mit No. 733-5

DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF SURFACE MINE RECLAMATION
INSPECTION
REPORT

Drainage Permit No. 7974 SMI

Mine Inspection No. 54

Reinspection No. 1

Company <u>The General Crushed Stone Co</u>		Mine Location: County <u>Rucks</u>	Township <u>East Rockhill</u>
Mining Permit Acres Affected <u>15</u>		Drainage Permit Acres Affected <u>30</u>	
Status of Operation: Active <input checked="" type="checkbox"/>	Inactive <input type="checkbox"/>	Not Started <input type="checkbox"/>	

1. Is this operation in compliance with the Safety Rules and Regulations? YES ___ NO ___ NOTED X
2. Is this mine operating in compliance with the conditions of the mining permit? YES ___ NO ___ NOTED X
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES ___ NO ___ NOTED X

REMARKS AND RECOMMENDATIONS: Water sample #2137 taken at discharge point as located on the Ruckhill property map dated 4-28-72. Water cloudy. Topsoil and subsoil - minimal amount available, the diabase crops as high boulders.

Prior to starting the top lift, a road will be constructed for the drill, etc. and the operator plans to attempt constructing a diversion ditch above the H/W in conjunction with building the access road.

No combustible material permitted within 25 feet of magazines

3rd lift started - a 25 foot bench is to be maintained between successive faces. 50 ft. H/W's

Company Official Contacted <u>Joseph P. Civial</u>	Title <u>Supt.</u>
Mine Inspector <u>Paul T. Surfass</u>	Inspection Date <u>3-23 & 31-77</u>

INSPECTORS' RECOMMENDATIONS TO BUREAU: Water sample # PS 2137 submitted to the Harrisburg Laboratory for analysis - if the sample does not meet the Water Quality standards this operator is to be charged with the violation.