

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF MINING AND RECLAMATION

Mine Name Rockhill Quarry
Weather Summer - 50°F
610-0253-4071

INSPECTION REPORT
NONCOAL

Date 3/25/98

On Site Times PM

PERMITTEE <u>Milestone Materials, Inc.</u>	TOWNSHIP <u>East Rockhill</u>	COUNTY <u>Bucks</u>	PERMIT NO. <u>79745m1</u>
ADDRESS <u>P.O. Box 231</u> <u>Easton, PA 18044</u>	VIOLATION HISTORY - NOV'S - CO'S	VIOLATIONS NOTED <input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> PREVIOUS VIOLATIONS: COMPLIANCE ORDER <input type="checkbox"/> CORRECTED <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> UNCORRECTED <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>	LICENSE NO. & EXP. DATE <u>3-00679 9/30/98</u> OPERATIONAL STATUS <u>Active</u>

GENERAL MINING INFORMATION: Large Noncoal Small Noncoal _____ Complete Partial or Followup _____

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: Dialing - Open pit measuring
~ 1500 ft (457.2m) x 900 ft (274.32m) x ~ 250 ft (76.2m) @ -5 levels
103.2 (41.77ha)

b. Acreage (total): Bonded 103.2 (41.77ha) Affected 18.3 (4.68ha) Regraded - Reclaimed -

c. Equipment-Use & Conditions: Processing Plants

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers) (no recent blasting)

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining				NA	730 Concurrent Reclamation			
<input checked="" type="checkbox"/>	701 Signs and Markers				NA	731 Backfilling and Grading			
NA	702 Casing and Sealing Drilled Holes				NA	733 Covering Coal and Acid/Toxic Mat.			
<input checked="" type="checkbox"/>	703 Topsoil-Rem/Sto/Hndlng				NA	735 Revegetation			
NA	704 Effluent Standard				NA	742 Permanent Mining Cessation			
NA	706 Diversions and Conveyance				<input checked="" type="checkbox"/>	743 Haul Roads/Restoration			
<input checked="" type="checkbox"/>	707 Sediment Control Measures				<input checked="" type="checkbox"/>	745 Support Facilities			
NA	708 Treatment Facilities				<input checked="" type="checkbox"/>	749 General Safety			
NA	709 Sedimentation Ponds				<input checked="" type="checkbox"/>	753 Permit Conditions			
<input checked="" type="checkbox"/>	710 Discharge Structures				NA	754 Temporary Mining Cessation			
NA	711 Acid and Toxic Forming Spoil				NA	755 Closing Underground Mine Openings			
NA	712 Impoundments				<input checked="" type="checkbox"/>	756 Distance Limitations-Barriers			
<input checked="" type="checkbox"/>	713 Dams, Ponds-Design/Const./Maint.				<input checked="" type="checkbox"/>	757 Bench Development			
<input checked="" type="checkbox"/>	715 Water Monitoring-Ground/Surface				<input checked="" type="checkbox"/>	758 Permit Line Setback			
NA	717 Water Rights and Replacement				NA	759 Stability Analysis			
NA	718 Water Discharge-Underground Mine				NA	760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement				NA	761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes				NA	762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: 1) T.D. area is part of the permitted area is adequately delineated, 2) The site is well maintained with no illegal mining activity on site, 3) The pit remains water filled, 4) Ponds and washwater basins remain properly maintained, 5) There are no erosion and reclamation problems evident at this time, 6) There is no violation history for the past 2 years.

Person Contacted <u>Copy to be mailed</u>	Title	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature	Investigator Signature & I.D. No. <u>Christina Kula</u>	Range of Samples Collected _____ to _____