ER–MR–5.7: Rev. 1/90

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

Date 3-4-94

Mine Name ROCK HILL

Weather Cloudy

INSPECTION REPORT NONCOAL

On Site Times [illegible]

PERMITTEE	TOWNSHIP	COUNTY	PERMIT NO.
GENERAL Crushed STONE Company	E. ROCK HILL	BUCKS	7974SM1
ADDRESS P.O. BOX 231 1609 SULLIVAN TRAIL EASTON, PA 18042	VIOLATION HISTORY ____NOV'S ____CO'S	VIOLATIONS NOTED ☐ PREVIOUS VIOLATIONS: CORRECTED ☐ UNCORRECTED ☐	FOLLOW-UP INSP. REQUIRED ☐ COMPLIANCE ORDER ☐ 308 FTC ORDER ☐ CEASE ORDER ☐ OUTSTANDING ENFORCEMENT ☐
			LICENSE NO. & EXP. DATE 733 12-31-94
			OPERATIONAL STATUS ACTIVE

GENERAL MINING INFORMATION: Large Noncoal ✓ Small Noncoal ____ Complete ✓ Partial or Followup ____

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: 1500X900X250-5 LIFTS OPEN PIT QUARRY

b. Acreage (total): Bonded 103.5 Affected ALL Regraded 0 Reclaimed 0

c. Equipment-Use & Conditions: SAME

d. Contract Miner ☐ yes ☑ no e. Blasting at Site ☑ yes ☐ no (Explain yes answers) NONE

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg	Viol.	Comp. Date
✓	700 Unauthorized Mining					730 Concurrent Reclamation			
	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Sto/Hndlng					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures					745 Support Facilities			
	708 Treatment Facilities					749 General Safety			
	709 Sedimentation Ponds					753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Undergound Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
	723 Blasting Requirement					761 Postmining Land Use			
	727 Disposal of Solid Wastes					762 Cleanup			
	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: NO ONE ON SITE

ENTRANCE GATE LOCKED 930 AM

Person Contacted	Title	Discharge/Seeps ☐ yes ☑ no
	FILE	Samples Collected ☐ yes ☑ no
		Range of Samples Collected ____ to ____
Signature Copy		Investigator Signature & I.D. No. James Carpenter 4 5 0 6

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.