



**COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL PROTECTION  
BUREAU OF MINING PROGRAMS**

Version: 2.3.0

**Mining Activities Inspection Report**

<b>Inspection Type</b>	RTNC - Routine/Complete Inspection	<b>Permit Number</b>	7974SM1
<b>DEP Office</b>	EP DMO Pottsville Dstr Mng Off	<b>NPDES Number</b>	PA0594121
<b>Permittee Name</b>	HANSON AGGREGATES PA LLC	<b>PF Name</b>	HANSON AGGREGATES PA ROCK HILL QUARRY
<b>Address 1</b>	7660 IMPERIAL WAY	<b>Permit Type</b>	IMMO - Industrial Mineral Mining Operation
<b>Address 2</b>		<b>Permit Kind</b>	LARGE - Surface Large
<b>City</b>	ALLENTOWN	<b>License Number</b>	24143
<b>State/ZIP Code</b>	PA 18195-1016	<b>Permit Status</b>	ACTIV - Active
<b>Arrival Date / Time</b>	11/07/2019 11:28 AM	<b>Municipality</b>	East Rockhill Township
<b>Depart Date / Time</b>	11/07/2019 12:11 PM	<b>County</b>	Bucks
<b>Inspection ID</b>	2996013	<b>GP12 Permit Number</b>	
<b>Contract Operator Name</b>		<b>Contract Operator License Number</b>	

**Inspector Details**

<b>Inspector Name:</b>	(608058) - AMIEE BOLLINGER	<b>Inspector Telephone Number:</b>	6109160100	<b>Inspector Email:</b>	ambollinge@pa.gov
------------------------	----------------------------	------------------------------------	------------	-------------------------	-------------------

**Expiration Dates**

<b>Mining License</b>	12/31/2020	<b>Contractor License</b>	08/31/2020
<b>Mining Permit</b>	07/19/2023 PENDING	<b>NPDES Permit</b>	07/19/2023 PENDING

**Inspection Result**

NOVIO - No Violations Noted

Findings

**Total Authorized Acreage**

<b>Active:</b>	103.20	<b>Support:</b>	
<b>Stage 1:</b>		<b>Stage 2 Eligible:</b>	
<b>Stage 2 Approved:</b>		<b>Stage 3:</b>	

**Erosion & Sedimentation**

<b>Approved E&amp;S Plan</b>	<input checked="" type="checkbox"/> Inspected	<b>Discharge Structure</b>	<input checked="" type="checkbox"/> Inspected
<b>Sediment Ponds/Dams</b>	<input checked="" type="checkbox"/> Inspected		

**Operations**

<b>Haul Roads</b>	<input checked="" type="checkbox"/> Inspected	<b>Mining Operation</b>	<input checked="" type="checkbox"/> Inspected
<b>Permit Conditions</b>	<input checked="" type="checkbox"/> Inspected	<b>Signs and Markers</b>	<input checked="" type="checkbox"/> Inspected
<b>Unauthorized Mining</b>	<input checked="" type="checkbox"/> Inspected		

**Reclamation**

<b>General Backfilling</b>	<input checked="" type="checkbox"/> Inspected	<b>Permit Conditions</b>	<input checked="" type="checkbox"/> Inspected
<b>Reclamation Plan</b>	<input checked="" type="checkbox"/> Inspected		

**Mining Area/Bonding**

<b>Adequate Bonding</b>	<input checked="" type="checkbox"/> Inspected		
-------------------------	---	--	--

**Compliance**

<b>Pattern Of Violations</b>	<input checked="" type="checkbox"/> Inspected		
------------------------------	---	--	--

This Report is official notification that a representative of the Department of Environmental Protection has conducted an investigation of your operation. Violations observed by the Department have been noted on this report form.

If the Department uncovers any violations based on laboratory reports or further consideration of the conditions described in this report, the District Office will notify you of such violations in writing.

If an order was issued by the Department, you will be provided with a written confirmation of that order. You should not wait until you receive this confirmation Order before taking appropriate action.

This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal actions for any violation noted herein.

General Comments

No activity observed. Minimal discharge was clear.