

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF MINING AND RECLAMATION

Mine Name Rock Hill Quarry
Weather Sunny - 60°F

INSPECTION REPORT
NONCOAL

Date 10/2/88
On Site Times 1410 -

PERMITTEE <u>Anderson Materials, Inc.</u>	TOWNSHIP <u>E. Rockhill</u>	COUNTY <u>Bucks</u>	PERMIT NO. <u>79743191</u>
ADDRESS <u>P.O. Box 231 Eaton, PA 18044</u>	VIOLETION HISTORY <u>0 NOV'S</u> <u>0 CO'S</u>	VIOLETIONS NOTED <input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> PREVIOUS VIOLATIONS: COMPLIANCE ORDER <input type="checkbox"/> CORRECTED <input type="checkbox"/> UNCORRECTED	LICENSE NO. & EXP. DATE <u>7-00679 9/30/88</u> OPERATIONAL STATUS <u>Active</u>

GENERAL MINING INFORMATION: Large Noncoal Small Noncoal Complete Partial or Followup

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: Diameter - 1000 ft across
4150' (1265.2m) x 500' (152.4m) x 250' (76.2m) - 5 lifts
1100' (41.77m)

b. Acreage (total): Bonded 100.0 Affected 10.0 Regraded - Reclaimed -

c. Equipment-Use & Conditions: Running Plants, dust system operational.

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers) No recent blasting

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
/	700 Unauthorized Mining				/	730 Concurrent Reclamation			
/	701 Signs and Markers				/	731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat.			
/	703 Topsoil-Rem/Sto/Hnding					735 Revegetation			
/	704 Effluent Standard				/	742 Permanent Mining Cessation			
/	706 Diversions and Conveyance				/	743 Haul Roads/Restoration			
/	707 Sediment Control Measures				/	745 Support Facilities			
	708 Treatment Facilities				/	749 General Safety			
/	709 Sedimentation Ponds				/	753 Permit Conditions			
/	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments				/	756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const./Maint.					757 Bench Development			
/	715 Water Monitoring-Ground/Surface				/	758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
/	723 Blasting Requirement					761 Postmining Land Use			
/	727 Disposal of Solid Wastes					762 Cleanup			
/	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: ① This inspection was conducted only.
② The quarry was not operating during this inspection. There were no stockpiles of processed stone observed.
③ A small gate was broken at the entrance preventing automobile admission.

Person Contacted (via phone call) Title <u>Mr. Tim Poppenberg</u> <u>Env. Mgr.</u>	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no - <u>Not observed.</u> Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Range of Samples Collected <u>-</u> to <u>-</u>
Signature <u>To be printed</u>	Investigator Signature & I.D. No. <u>Christina Kula</u> <u>9556</u>

COMMENTS AND RECOMMENDATIONS

Mine Name Roakhill Quarry

Date 10/2/98

PERMITTEE <u>Milestone Materials Inc.</u>	TOWNSHIP <u>E. Roakhill</u>	COUNTY <u>Bucks</u>	PERMIT NO. <u>79745M1</u>

(1) The water elevation in the pit appeared to be high. Milestone materials should keep an eye on the water level of this pit to prevent overflows or possible flooding.

(2) Signs warning people of a quarry (hazard) are missing. More signs warning people of the hazard should be posted.

(3) There was no physical barrier prevention on embankment terraces from walkways off of a highwall. Milestone materials should submit a plan to the DEP which discusses how this danger will be abated. The trail which goes around the pit appeared to be traveled frequently for bikes, horses, and mountain bike riders. A campsite was also observed along a highwall.

(4) Milestone Materials is reminded that a minimum 500 tons per acre of mined material must be sold to keep the permit active. I observed no stockpiles of material onsite which exceed building. Milestone materials should submit to DEP documentation regarding the sales for 1998 and contact me when any future sales pit is to take place. I would like to be onsite when the next shipment of material is to leave the site.

Person Contacted Mr. Timi Poppeberg Title Env. Mgr.

Signature To be mailed

Investigator Signature & I.D. No. Christina Kula 4 5 5 6

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.