

2642541



COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF MINING PROGRAMS

INSPECTION REPORT NONCOAL

Date: 9/7/2017

Mine Name Rock Hill Quarry Weather Overcast 61 F

Complete [x] Partial [ ]

On Site Times 1215 - 1245

PERMITTEE Hanson Aggregates Pennsylvania, LLC TOWNSHIP East Rockhill COUNTY Bucks PERMIT NO. 7974SM1

GENERAL MINING INFORMATION: Large [x] Small 10,000 [ ] 2,000 [ ] GP 105 [ ] GP 103 [ ] Expiration Date:

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: Argillite open pit- water filled pit- ~1500' x ~900' x ~250'

b. Equipment-Use & Conditions: FEL- good condition

c. Contract Miner: Yes [ ] No [x] Name: d. Approved Blast Plan: Yes [x] No [ ] Is there blasting today? Yes [ ] No [x]

Table with columns: Approved Acres, Approved Pit Volume, Progress of Reclamation, Liability. Includes rows for Mining Area, Disturbed not planted, Affected acres, Selective Grading of Highwall.

Highwall Bond (Blasting to achieve reclamation) Approved/Affected. Table with columns for distance ranges: <20 ft., >20<30 ft., >30<40 ft., >40<50 ft., >50 ft.

PERFORMANCE STANDARDS NONCOAL

Table with columns: Obs., STANDARD, PC or Reg., Viol., Comp. Date. Lists standards such as Unauthorized Mining, Mining License, Signs and Markers, etc.

COMMENTS AND RECOMMENDATIONS: This complete inspection was conducted solo. The gates were locked and no activity was observed.

Violation History: None for the past two years.

Person Contacted None Title Signature Discharge/Seeps: [ ] yes [x] no Range of Samples Collected Investigator Signature Amiee Bollinger Collector ID No. 4519 Employee ID No. 608058

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

[ ] White - District File [ ] Yellow - Permittee [ ] Pink - Inspector