



September 20, 2019

Hanson Aggregates Pennsylvania, LLC  
Attn: Mr. Andrew Gutshall, P.G., Environmental Manager  
7660 Imperial Way  
Allentown, PA 18195-1040

Re: Rock Hill Quarry Naturally Occurring Asbestos Sampling  
SMP No. 7974SM1  
East Rockhill Township  
Bucks County

Dear Mr. Gutshall:

The Department has reviewed the results of the analytical testing for natural occurring asbestos conducted by both Hanson Aggregates Pennsylvania, LLC and the Department. After reviewing the results and the information available to the Department, the following additional information and testing is requested:

1. Please conduct Transmission Electron Microscopy using EPA Method 600/R-93/116 (or equivalent) analysis for asbestos on all rock samples collected at the Rock Hill Quarry.
2. Please prepare suitable samples for petrographic analysis.
3. Please resample at all the water sampling locations using EPA Method 100.1.
4. By October 7, 2019, please provide the sample locations (boulder, core and aggregate) for all rock samples.

Sincerely,

A handwritten signature in black ink that reads "Gary A. Latsha". The signature is written in a cursive style with a large initial "G".

Gary A. Latsha  
District Mining Manager  
Bureau of District Mining Operations