



## NARRATIVE REPORT FORM

Facility Name: Glenwood Drive and Walker Road Primary Facility ID: 881609

Inspection Date: 4-18-25		Inspection Time: 8:55		Lat/Long:	
Program: ECB		<input type="checkbox"/> Storage Tanks		<input type="checkbox"/> HSCA	
				<input checked="" type="checkbox"/> LRP	
Owner Name: Energy Transfer			Inspection ID:		Site ID:
Facility Location (911) Address: Glenwood Drive and Walker Road Washington Crossing, PA 18977				Municipality: Upper Makefield Twp.	
				County: Bucks	
Responsible Official Name: Brad Fish				Responsible Official Address:	
Title: Senior Environmental Specialist Emergency Response & Remediation				100 Green Street Marcus Hook, PA 19061	
Responsible Official Telephone: 610-859-6297				Interviewee Name:	
Email Address:				Affiliation:	
bradford.fish@energytransfer.com				Email Address:	

### Narrative:

DEP personnel: Simon Mullen, Caroline Spengler

DEP arrived at the Mt. Eyre neighborhood at 8:55. GES personnel/vehicles were not observed in the neighborhood, so DEP drove to the ET trailer. An ET employee was onsite to distribute water, no one else was present at the trailer. The ET employee provided contact info for GES personnel. DEP called GES personnel and were informed that the gauging crew would be onsite shortly. DEP drove back to the Mt. Eyre neighborhood and waited near [REDACTED]. GES arrived onsite at 9:30. DEP observed GES conduct wellhead screening, gauging, and bailing operations at [REDACTED] and [REDACTED].

Address	Time	PID (ppm)	DTP (ft.)	DPW (ft.)	LNAPL (ft.)
[REDACTED]	9:34	1017	24.73	24.80	0.07
[REDACTED]	10:47	218.8	26.94	26.95	0.01

### Observations:

[REDACTED] Resident came out and said hello to GES and DEP personnel at beginning of gauging and then went back inside. The bailer got stuck in the well. After approximately 1 hour, the bailer was able to be extracted. LNAPL was bailed and the resultant thickness measured 0.02-feet.



[REDACTED] After bailing, a LNAPL sheen remained.

DEP departed at 11:05

DEP Representative Name Simon Mullen		DEP Representative Signature Simon Mullen, P.G. <small>Digitally signed by Simon Mullen, P.G. Date: 2025.04.21 14:35:38 -04'00'</small>		Title Licensed Professional Geologist		Date: 4-21-25	
						Telephone: 484-250-5770	
Signature by the person interviewed does not necessarily imply concurrence with the findings on this report but does acknowledge that the person was shown the report or that a copy was left with the person.							
Interviewee Name		Interviewee Signature		Title		Date:	
						Telephone:	

Facility Name: Glenwood Drive and Walker Road Primary Facility ID: 881609

MAPS / PHOTOGRAPHS / ATTACHMENTS



DEP Representative Name Simon Mullen	DEP Representative Signature Simon Mullen, P.G. <small>Digitally signed by Simon Mullen, P.G. Date: 2025.04.21 14:36:14 -0400'</small>	Title Licensed Professional Geologist	Date: 4-21-25 Telephone: 484-250-5770
Signature by the person interviewed does not necessarily imply concurrence with the findings on this report but does acknowledge that the person was shown the report or that a copy was left with the person.			
Interviewee Name	Interviewee Signature	Title	Date:
			Telephone:

Facility Name: Glenwood Drive and Walker Road

Primary Facility ID: 881609



Bailing potable well at [REDACTED]  
4-21-25 @ 9:37



Recovering bailer from [REDACTED]  
4-21-25 @ 10:11



Screening wellhead at [REDACTED]  
4-21-25 @ 10:44



Bailing potable well at [REDACTED]  
4-21-25 @ 10:48

DEP Representative Name Simon Mullen	DEP Representative Signature Simon Mullen, P.G. <small>Digitally signed by Simon Mullen, P.G. Date: 2025.04.21 14:36:47 -04'00'</small>	Title Licensed Professional Geologist	Date: 4-21-25 Telephone: 484-250-5770
Signature by the person interviewed does not necessarily imply concurrence with the findings on this report but does acknowledge that the person was shown the report or that a copy was left with the person.			
Interviewee Name	Interviewee Signature	Title	Date: Telephone: