



NARRATIVE REPORT FORM

Facility Name: Glenwood Drive and Walker Road

Primary Facility ID: 881609 _____

Inspection Date: 9-29-25		Inspection Time: 11:00		Lat/Long:	
Program: ECB		☐ Storage Tanks		☐ HSCA	
				☒ LRP	
Owner Name: Energy Transfer			Inspection ID:		Site ID:
Facility Location (911) Address: Glenwood Drive and Walker Road Washington Crossing, PA 18977				Municipality: Upper Makefield Twp.	
				County: Bucks	
Responsible Official Name: Brad Fish				Responsible Official Address:	
Title: Senior Environmental Specialist Emergency Response & Remediation				100 Green Street Marcus Hook, PA 19061	
Responsible Official Telephone: 610-859-6297					
Email Address: bradford.fish@energytransfer.com					
Entities Present: DEP – Rebecca Flannery ET – Wassim Saad, Nancy Sadlon and Ryan Dipper PHSMA – Marta Reindeau and Joe Willoughur National Energy Fuel Services (NEFS) (3 rd party inspector) – Tim Wedig Otis Minnesota Services – Excavation contractor Earth Data – Dave Fennimore					
Purpose: Observing start of anomaly investigation in pipeline identified during routine inspection in front of [REDACTED]					
Weather: Partly sunny; 70's					
Narrative: - I arrived in front on [REDACTED] at 11:00. - Excavation to locate the pipeline had already begun, and the weld location was trying to be located. - It was explained to me that when the tool is pushed through the pipe to inspect it, it referenced any anomalies by the distance from a certain weld. - The location of the weld is known along the pipe, ET just needed verification the location of it so that the distance from the weld could be measured to the anomalies detected. The pipe is located approximately 4.5 feet below ground surface. - The weld was uncovered and the coating taken off to verify the weld. Once verified, a distance of 25 feet was measured towards the south. - Soil was excavated on both sides of the pipe for the whole 25 feet. - At 12:21, I observed a helicopter circling above the excavation, which had the CBS 3 logo on it. - During the excavation, I noticed some dark brown to black material being removed. After it was placed on the pile, I went to investigate what it was. Looking at it, I determined it was broken up slabs of black shale. I did not detect any odors. - About two feet beneath of the bottom of the pipe, about 7.5 feet bgs, I observed water flowing into the excavation. I did not notice any sheen on the water or any odors from the excavation. - I was asked by an employee from Otis what they should do with the water in the excavation. I told him I would find out and let him know. I was not able to get an answer before I departed the site. - While the additional soil was being excavated, I noticed that the excavator had reached bedrock. - There was also noticeable weathered shale from the bottom of the pipe to the groundwater. - After the soil was excavated, it was protected with orange snow fence and caution tape. - The plans for tomorrow were remove the coating at the three noted anomalies and inspect them.					

DEP Representative Name Rebecca Flannery	DEP Representative Signature Rebecca Flannery Digitally signed by Rebecca Flannery Date: 2025.09.30 14:10:25 -0400	Title Geoscientist	Date: 9-30-25 Telephone: 484-250-5779
Signature by the person interviewed does not necessarily imply concurrence with the findings on this report but does acknowledge that the person was shown the report or that a copy was left with the person.			
Interviewee Name	Interviewee Signature	Title	Date: Telephone:



NARRATIVE REPORT FORM

Facility Name: Glenwood Drive and Walker Road

Primary Facility ID: 881609 _____

Narrative (continued):

Between 12:45 and 14:30, there were many residents from the neighborhood to observe the activities and Township representatives:

- Gary Shuster, the Upper Makefield Township Manager
- Tim Thomas and Ben Weldon who are Board Members for Upper Makefield Twp
- Congressman Ryan Fitzpatrick
- Senator Santarsiero

During the site visits, many residents came to speak with them, the PHMSA inspectors and myself.

I spoke to the resident at [REDACTED], where four groundwater monitoring wells were previously installed. [REDACTED] requested the drilling logs and other information from when the wells were installed on [REDACTED] property. I told [REDACTED] that I would verify I could and then sent it to [REDACTED].

I departed the site at 15:05.



DEP Representative Name Rebecca Flannery	DEP Representative Signature Rebecca Flannery Digitally signed by Rebecca Flannery Date: 2025.09.30 14:11:32 -04'00'	Title Geoscientist	Date: 9-30-25 Telephone: 484-250-5779
<i>Signature by the person interviewed does not necessarily imply concurrence with the findings on this report but does acknowledge that the person was shown the report or that a copy was left with the person.</i>			
Interviewee Name	Interviewee Signature	Title	Date: Telephone:

NARRATIVE REPORT FORM

Facility Name: Glenwood Drive and Walker Road

Primary Facility ID: 881609

MAPS / PHOTOGRAPHS / ATTACHMENTS



DEP Representative Name Rebecca Flannery	DEP Representative Signature Rebecca Flannery Digitally signed by Rebecca Flannery Date: 2025.09.30 14:11:45 -0400	Title Geoscientist	Date: 9-30-25 Telephone: 484-250-5779
Signature by the person interviewed does not necessarily imply concurrence with the findings on this report but does acknowledge that the person was shown the report or that a copy was left with the person.			
Interviewee Name	Interviewee Signature	Title	Date: Telephone:

NARRATIVE REPORT FORM

 Facility Name: Glenwood Drive and Walker Road

 Primary Facility ID: 881609


Hand clearing around pipeline with shovels
9-29-25 @ 11:08



Magnetic tool used to locate the weld
9-29-25 @ 11:11



Weld in pipe located and coating removed
9-29-25 @10:34



Black shale from excavation
9-29-25 @11:48

DEP Representative Name Rebecca Flannery	DEP Representative Signature Rebecca Flannery Digitally signed by Rebecca Flannery Date: 2025.09.30 14:11:58 -0400	Title Geoscientist	Date: 9-30-25 Telephone: 484-250-5779
<i>Signature by the person interviewed does not necessarily imply concurrence with the findings on this report but does acknowledge that the person was shown the report or that a copy was left with the person.</i>			
Interviewee Name	Interviewee Signature	Title	Date:

NARRATIVE REPORT FORM

 Facility Name: Glenwood Drive and Walker Road

 Primary Facility ID: 881609


Representative Ryan Fitzpatrick conversing with PHSMA
9-29-25 @ 13:38



Bedrock encountered in excavation, approximately 7.5 feet bgs.
9-29-25 @ 13:46



Water in excavation, no sheen or odor noticed
9-29-25 @ 14:23



Uncovered pipeline from weld to areas of identified anomalies
9-29-25 @ 14:26

DEP Representative Name Rebecca Flannery	DEP Representative Signature Rebecca Flannery Digitally signed by Rebecca Flannery Date: 2025.09.30 14:13:13 -0400	Title Geoscientist	Date: 9-30-25 Telephone: 484-250-5779
<i>Signature by the person interviewed does not necessarily imply concurrence with the findings on this report but does acknowledge that the person was shown the report or that a copy was left with the person.</i>			
Interviewee Name	Interviewee Signature	Title	Date:

NARRATIVE REPORT FORM

 Facility Name: Glenwood Drive and Walker Road

 Primary Facility ID: 881609


Anomaly locations marked with yellow paint
9-29-25 @ 14:48



Orange snow fence set up around excavation
9-29-25 @ 14:48

Intentionally Left Blank

Intentionally Left Blank

DEP Representative Name Rebecca Flannery	DEP Representative Signature Rebecca Flannery Digitally signed by Rebecca Flannery Date: 2025.09.30 14:12:27 -0400	Title Geoscientist	Date: 9-30-25 Telephone: 484-250-5779
<i>Signature by the person interviewed does not necessarily imply concurrence with the findings on this report but does acknowledge that the person was shown the report or that a copy was left with the person.</i>			
Interviewee Name	Interviewee Signature	Title	Date: